

ASS. REC BY: Tau J M

REF:

C 56/115 220/2051/Tuy 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 975K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT8618E Yr Regn: 2015 / June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz CLA180 c.c. 1595

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 11294 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 117 34 22 N* 216610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 40 R18

R: 225 / 40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 02/12/22

Survey held at Chen Guan

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Report Format: _____

Lump Sum / L.B.R. / _____

☐ : Interview (\$ _____)

S + RS \$ _____

☐ : Tech. Invs (\$ _____)

Photos _____

☐ : Weekend (\$ _____)

Others _____

TOTAL _____

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Dec 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Chew Goon Motor/SKT8618E/01/12/2022 15:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Grille	0.00	0.00	*350.00 F <i>Car</i>
2	1		*Grille Emblem	0.00	0.00	*75.00 F <i>mis</i>
3	1		*Grille Emblem Base Bracket	0.00	0.00	*38.00 F <i>gas</i>
4	1		*Front Bumper	0.00	0.00	*650.00 F <i>de</i>
5	10		*Front Bumper Clips	0.00	0.00	*40.00 F <i>ny</i>
6	2		*Front Bumper Brackets	0.00	0.00	*250.00 F <i>?</i>
7	1		*Front Bumper Sponge	0.00	0.00	*100.00 F <i>de</i>
8	1		*Front Bumper Reinforcement	0.00	0.00	*225.00 F <i>?</i>
9	1		*Front Bumper Center Air Grille	0.00	0.00	*76.00 F <i>?</i>
10	1		*Front Bumper Sensor	0.00	0.00	*135.00 F <i>nu</i>
11	4		*Front Bumper Sensor Holders	0.00	0.00	*100.00 F <i>nu</i>
12	1		*Front Bumper Top Core	0.00	0.00	*150.00 F <i>?</i>
13	1		*Front Bumper Top Beam	0.00	0.00	*220.00 F <i>?</i>
14	2		*Front Bumper Inner Side Cores	0.00	0.00	*90.00 F <i>?</i>
15	2		*Front Bumper Top Retainers	0.00	0.00	*50.00 F <i>dis</i>
16	1		*Front Bumper Inner Collision Preventive Sensor	0.00	0.00	*135.00 F <i>?</i>
17	1		*Front Bumper Inner Collision Preventive Sensor Module	0.00	0.00	*1,320.00 F <i>?</i>
18	1		*Front Bumper Emblem	0.00	0.00	*30.00 F <i>nu</i>
19	1		*Front Bumper Top Rubber Seal	0.00	0.00	*30.00 F <i>de</i>
20	1		*Front Bumper Number Plate Holder	0.00	0.00	*80.00 F <i>de</i>
21	2		*Headlamps	0.00	0.00	*2,900.00 F <i>?</i>
22	1		*Support Panel	0.00	0.00	*275.00 F <i>?</i>
23	1		*Air Con Condenser	0.00	0.00	*540.00 F <i>ht</i>
24	1		*Air Con Condenser Side Air Guide	0.00	0.00	*120.00 F <i>?</i>
25	1		*Turbo Inter-Cooler	0.00	0.00	*450.00 F <i>?</i>
26	1		*Radiator	0.00	0.00	*590.00 F <i>?</i>
27	1		*Bonnet	0.00	0.00	*800.00 F <i>Rx</i>
28	1		*Front Number Plate	0	0.00	*45.00 FS <i>Car</i>

F=Franchise part, S=SpcNett.

Sub Total (\$)	9,864.00
+ Margin on L,N Items 10.00% (\$)	981.90
Total Parts (\$)	10,845.90

Chew Goon Motor/SKT8618E/01/12/2022 15:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To Conduct Electrical Check, Focus Headlamp	New	30.00 ✓
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas	New	100.00 ✓
3	To Remove / Refit, Radiator System, Bleed, Refill Coolant	New	50.00 ?
4	Labour Charge - Panel Beating, Repairing of Front Chassis, Inner Panel, Front Fender & Part Replacement	New	600.00 500
5	To Respray Affected Areas	New	1,400.00 600
Gross Labour Cost (\$)			2,180.00

Chew Goon Motor/SKT8618E/01/12/2022 15:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfik 97495749
Not Authorised Ex-tna
04 days 02/12/22 -
1/5 Reming after repair