



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 3502S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	DENTED	689.40	689.40
1	HEADLAMP RH (CONSISTENT)	CUT	727.10	727.10
1	FRONT RH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,485.40	-
1	FRONT RH DOOR WEATHERSTRIPE (CONSISTENT)	NOT NECESSARY	228.10	-
1	FRONT RH DOOR HINGE (CONSISTENT)	NOT NECESSARY	112.10	-
1	FRONT RH STEP GARNISH (CONSISTENT)	CUT	245.90	245.90
	LESS 25% DISCOUNT		-	-415.60
			3,488.00	1,246.80
<b>SPECIAL NETT ITEMS</b>				
1	FRONT RH DOOR COMPANY DETAIL STICKER (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT RH DOOR ADVERTISEMENT STICKER (SN) (CONSISTENT)	NECESSARY	380.00	250.00
			410.00	280.00
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR.		600.00	400.00
	SPRAY PAINTING.		600.00	400.00
	WIRING.		50.00	30.00
	TO APPLY TUFF COAT.		100.00	30.00
	TO TRANSFER DOOR FITTINGS.	NOT NECESSARY	150.00	-
			1,500.00	860.00
<b>GRAND TOTAL</b>			<b>5,398.00</b>	<b>2,386.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,900.00</b>

Report Ref No. CS/ASM22012052/Aqp3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.