

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012057/AVP3Q2**Date:** 03/03/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00120192200

**Claimant Vehicle
No :** GBL6948P**Insured
Vehicle No :** YQ8229U

Date of Loss: 23/11/2022

Nature of Claim: TP

Claim
No: SNM22D208618/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBL6948P**

Make & Model: TOYOTA HIACE, 2.0 DX (A)

Engine No: 1TR2393102

Reg. Date: 17/01/2022 (Man. Year: 2021)

Chassis No: TRH2005048895

Colour: Silver

Odometer: 22620 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15

Rear Tyre Size: 195/80 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,727.72	2,289.35	438.37	16.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	450.00	350.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,527.72	2,739.35	788.37	22.35
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	3,527.72	2,200.00	1,327.72	37.64
+ GST 8.00/8.00% (S\$)	282.22	176.00	106.22	37.64
Nett Amount (S\$)	3,809.94	2,376.00	1,433.94	37.64

INSPECTION

Date of Assignment: 01/12/2022

Date Inspected: 15/12/2022 Inspected At:

People's Vehicle Recovery Service (HQ)
Blk 3023A Ubi Rd 1, #01-60
Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	213	TOYOTA HIACE 2.0 DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL6948P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR R/H FRT	Dented	1,887.20 FL	*1,415.00 FL
2	1		*DOOR OUTER MOULDING R/H FRT	Deformed	230.80 FL	*230.80 FL
3	1		*SIDE MIRROR R/H	Cut	1,492.30 FL	*1,380.00 FL
4	1		*BODY LETTERING	Necessary	20.00 FS	*20.00 FS
					Sub Total (S\$)	3,630.30
					- List Item Discount on L Items 25.00/25.00% (S\$)	902.58
					Total Parts (S\$)	2,727.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	450.00	200.00
2	SPRAY PAINTING ACCIDENT AFFECTED PARTS	New	350.00	250.00
Gross Labour Cost (S\$)			800.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >