



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300971

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/02/2023
Reference CC6/CTI22012066/Kya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SME 5644D
Insured Veh. SMA 3464R
Claim No. SNM22D208539/C02
Policy No. DMHCSNW00014222100
Accident Date 27/11/2022
Inspection Date 29/11/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22012066/Kya3q2 Date: 18/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 3464R	Veh. Inspected	SME 5644D	
Policy No.	DMHCSNW00014222100	Coverage (\$)	0.00	
Claim No.	SNM22D208539/C02	Excess (\$)	0.00	
Assign From		Assign Date	29/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q2 TFSI (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZGA6JA101679	Colour	YELLOW	
Odometer	48533 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	GOODYEAR	8 mm	
L/H Front Tyre	225/45 R18	GOODYEAR	8 mm	
R/H Rear Tyre	225/45 R18	GOODYEAR	8 mm	
L/H Rear Tyre	225/45 R18	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2022	Inspection Date	29/11/2022	
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 5644D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	812.95	812.95
1	FRONT BUMPER LOWER SPOILER	DENTED	315.75	315.75
1	FRONT BUMPER LH FOG LAMP COVER	CUT	179.10	179.10
1	FRONT BUMPER LOWER GRILLE	CRACKED	205.70	205.70
1	FRONT BUMPER LH SIDE RETAINER	DISTORTED	41.35	41.35
1	FRONT BUMPER INNER FOAM	SERVICEABLE	72.15	-
1	FRONT BUMPER INNER REINFORCEMENT	BENT	681.25	681.25
1	FRONT GRILLE ASSY	CUT	1,253.75	1,253.75
1	LH HEADLAMP (LED)	CUT	4,437.40	4,124.60
1	LH HEADLAMP WASHER NOZZLE	SERVICEABLE	115.65	-
1	LH HEADLAMP WASHER NOZZLE COVER	SERVICEABLE	41.10	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	901.95	-
1	FRONT LH FENDER LOWER WHEEL ARCH BLACK GARNISH	BUCKLED	312.75	312.75
	LESS 5% DISCOUNT		-468.54	-396.36
			8,902.31	7,530.84
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	45.00
			50.00	45.00
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT ,REPAIR AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF FRONT LH FENDER .		600.00	400.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		600.00	550.00
	TO CHECK WIRING AND LIGHTINGS.		40.00	20.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT .	NOT NECESSARY	60.00	-
			1,300.00	970.00
	GRAND TOTAL		10,252.31	8,545.84



RECOMMENDED COST OF REPAIRS			8,545.84
-----------------------------	--	--	----------

Report Ref No. CC6/CTI22012066/Kya3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 5644D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 5644D

RE-INSPECTION

