

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22012075/KYA3Q2
Date: 08/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100497222
Claimant Vehicle No :	SGQ3375B	Insured Vehicle No :	SLK2453M
Date of Loss:	30/11/2022	Nature of Claim:	TP
		Claim No:	1012155350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGQ3375B	Engine No:	R18A1720792
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61018207
Reg. Date:	11/01/2007 (Man. Year: 2006)	Odometer:	514251 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	CST 8 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 8 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,837.97	1,814.80	1,023.17	36.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,110.00	1,230.00	52.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,177.97	2,924.80	2,253.17	43.51
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	5,177.97	2,300.00	2,877.97	55.58
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,902.00		

INSPECTION

Date of Assignment:	02/12/2022		
Date Inspected:	05/12/2022	Inspected At:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	974.70 FL	*688.00 FL
2	1		*REAR BUMPER SIDE RETAINER	Cracked	73.40 FL	*73.40 FL
3	1		*REAR TAIL LAMP ASSY	Cracked	782.60 FL	*446.00 FL
4	1		*REAR FENDER	Bent	1,067.56 FL	*928.70 FL
5	1		*REAR FENDER QUARTER GLASS MOULDING	Necessary	574.20 FL	*82.40 FL
6	1		*TUBE WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,532.46	2,258.50
- List Item Discount on L Items 20.00/20.00% (\$)	694.49	443.70
Total Parts (\$)	2,837.97	1,814.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE PARTS ,REALIGN & PANEL BEAT THE AFFECTED AREAS	New	1,400.00	600.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
3	TO APPLY RUST PROOFING	New	100.00	30.00
4	TO REMOVE AND REFIT QUARTER WINDSCREEN GLASS	New	140.00	60.00
5	TO APPLY WATER PROOF SEALANT ON JOINTED PANELS	New	100.00	20.00
			Gross Labour Cost (\$\$)	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >