

(08/11/13) waf

ASS. REC. BY: Rajan

REF:

CC4/ASM 220 12077/Rpa³

033N

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: PA 270at Workshop m/s AT AUTOof 6, Sunher Road WanyuInsured: ASM

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 130K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PA 270 Yr Regn: 2017 109Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU LT 434P 7.83M c.cColour: GREEN A/C: Insured / Std / NI / NASp. Reading: 295715 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JALT 434PH 7000061Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5R: 8/10BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mmD.O.A. 30/11/22D.O.I. 17/02/23Survey held at AT AUTODes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 109K

Date/Time, File Pass to?

☐: Prell. Report☐: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS SI

) Photos

) Others

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)

Report Format: _____

Lump Sum / LBI: / \$

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	033N
Vehicle Details	
Vehicle No.:	PA27D
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2022
Vehicle Make:	ISUZU
Vehicle Model:	LT434P 7.8 SMT
Primary Colour:	Multicolor
Manufacturing Year:	2017
Engine No.:	6HK1698221
Chassis No.:	JALLT434PH7000061
Maximum Power Output:	-
Open Market Value:	\$98,872.00
Original Registration Date:	20 Oct 2017
First Registration Date:	20 Oct 2017
Transfer Count:	2
Actual ARF Paid:	\$4,944.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,809.00
COE Rebate Amount:	\$20,886.00
Total Rebate Amount:	\$20,886.00

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 Email: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 01.12.2022
Vehicle No: PA27D
Owner: GOH TRANSPORT SERVICES CO. PTE LTD
Date of Accident: 30.11.2022
Make & Model: ISUZU LT434P
Chassis No : JALLT434PH7000061

ESTIMATE FOR ACCIDENT VEHICLE NO PA27D

PARTS

1	1 Rear bumper <i>SEA</i>	\$3,420.00
2	1 Rear bumper bumper bracket <i>4x</i>	\$650.00
3	1 Rear tail lamp corner panel (repair)	\$0.00
4	1 Tail gate (repair)	\$0.00
SUB TOTAL		<u>\$4,070.00</u>
LESS 10 %		<u>\$407.00</u>
DISCOUNTED SUB TOTAL		<u>\$3,663.00</u>

S. NETT ITEM

SUB TOTAL	\$0.00
LESS 0 %	\$0.00
DISCOUNTED SUB TOTAL	<u>\$0.00</u>

LABOUR

1	Panel beating for replace and repair affected parts	<i>500</i> \$800.00
2	Spray painting on affected area for 3 colours X 3 panels	<i>600</i> \$1,000.00
3	Wiring charges & testing commissioning	<i>X</i> \$100.00
4	Apply putty and anti-corrosion to affected parts	<i>X</i> \$400.00
SUB TOTAL (LABOUR)		<u>\$2,300.00</u>

S.NET ITEM	\$0.00
SUB TOTAL (PARTS)	\$3,663.00
SUB TOTAL (LABOUR)	\$2,300.00
ESTIMATED GRAND TOTAL	\$5,963.00

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP

Rose
Hp 90010068

4 days

L/S

Resurvey after
repair

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: