

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012081/UVP3Q2**Date:** 13/12/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00002512201		
Claimant Vehicle No :	SMN5888U	Insured Vehicle No :	YQ1286A		
Date of Loss:	30/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208619/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMN5888U</b>	Engine No:	CZC162279
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI AT 5G13HZ (A)	Chassis No:	WVWZZZAUZHW121997
Reg. Date:	13/04/2017 (Man. Year: 2016)	Odometer:	95083 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,624.70	3,496.11	3,128.59	47.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	820.00	1,620.00	66.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,064.70</b>	<b>4,316.11</b>	<b>4,748.59</b>	<b>52.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,064.70</b>	<b>3,400.00</b>	<b>5,664.70</b>	<b>62.49</b>

INSPECTION

Date of Assignment:	09/12/2022	15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807
Date Inspected:	02/12/2022 Inspected At:	Repairer:Nineteen Autowerks Pte Ltd - Woodlands (HQ)
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2022)
<b>Parts:</b>	144	VOLKSWAGEN GOLF 1.4 TSI AT 5G13HZ (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMN5888U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed / Torn	1,041.58 FL	*1,041.58 FL
2	1		*REINFORCEMENT	Repair	500.86 FL	*- FL
3	1		*FRT BUMPER SPONGE	Not Necessary	146.44 FL	*- FL
4	10		*FRT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
5	1		*BUMPER INNER BRACKET LH	Cracked	60.69 FL	*60.69 FL
6	1		*BUMPER INNER BRACKET RH	Not Necessary	60.69 FL	*- FL
7	1		*BUMPER SIDE RETAINER LH	Cracked	24.70 FL	*24.70 FL
8	1		*BUMPER SIDE RETAINER RH	Not Necessary	24.70 FL	*- FL
9	4		*SENSOR BRACKET	Not Necessary	120.00 FL	*- FL
10	4		*SENSOR	Not Necessary	577.60 FL	*- FL
11	1		*FOG LAMP GRILLE LH	Repair	101.50 FL	*- FL
12	1		*H/LAMP LH	Cracked	3,818.52 FL	*2,087.95 FL
13	1		*FRONT FOGLAMP LH	Cracked	580.00 FL	*366.15 FL
14	1		*WIPER WASHER TANK	Cracked	253.50 FL	*253.50 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,360.78</b>	<b>3,884.57</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	736.08	388.46
<b>Total Parts (\$)</b>	<b>6,624.70</b>	<b>3,496.11</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	800.00	400.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	400.00
3	TO CHECK WIRING }	New	100.00	20.00
4	TO REMOVE AND REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING & RESETTNG HEADLAMP FOCUS }	New	160.00	0.00
5	TO PPLY UNDERCOATING FOR RUST PROOFING	New	80.00	0.00
6	TO APPLY TUFF COAT ON AFFECTED AREAS	New	150.00	0.00
7	DIGNOSTIC RESET	New	350.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,440.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >