

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012094/KYA3Q2**Date:** 18/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900104880
Claimant Vehicle No :	SMW6420G	Insured Vehicle No :	SJS6081H
Date of Loss:	26/11/2022	Nature of Claim:	TP
		Claim No:	9577315634SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW6420G	Engine No:	2ZR2H23374
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU103092829
Reg. Date:	30/11/2020 (Man. Year: 2020)	Odometer:	154525 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,306.67	1,359.62	947.05	41.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	470.00	1,150.00	70.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,926.67	1,829.62	2,097.05	53.41
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	3,926.67	1,450.00	2,476.67	63.07
+ GST 7.00/7.00% (S\$)	274.87	101.50	173.37	63.07
Nett Amount (S\$)	4,201.54	1,551.50	2,650.04	63.07
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,713.50		

INSPECTION

Date of Assignment:	02/12/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	02/12/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	488.50 FL	*488.50 FL
2	1		*REAR BUMPER LOWER GARNISH	Dented / Cut	576.80 FL	*576.80 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	336.20 FL	*336.20 FL
4	1		*REAR END PANEL	Repair	729.40 FL	*- FL
5	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- FL
6	1		*REAR BUMPER ANTENNA SENSOR	Cracked	78.00 FL	*78.00 FL
7	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
8	1		*REAR BUMPER REVERSE SENSOR	Scratched	600.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,858.90	1,729.50
- List Item Discount on L Items 25.00/25.00% (\$)	552.23	369.88
Total Parts (\$)	2,306.67	1,359.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS	New	600.00	200.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	700.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	0.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			1,620.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >