for the second s	
ASIS. RECIBY: TOUTH REF. CS/10>270	1.295/1048
ASS. RECISI. 12 TI	GNMENT
	Veh No: SLH 3410X Yr Regn: 2016, Oct
Estimated lost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
GD/TP / NS /TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: Wa Sevento c.c 2199.
To Inspect/Vehicle No:	Colour Rown A/C: Insured / Std / Ni / NA
at Workship m/s	0 //2
of	
Insured:	Eng/No: KWAPH816MG5210081
Policy No. MPC22P00252700	Gen. Cond: Good / Fair / Poor / Burnt
Claims No DMPC2200599H/CT	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insued: Excess: 0	Brake: Inbreer / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Pam / STD AJRim or
Make of Veh:	
	Tyre Size: F: 235/60K(8
(Policy Condition) Remark: The veh had commenced its N/S O/S	BS I DUN I EXNOVA I GY I-FS I LIZA MIC I OHTSU I PIR I SUMI I
repair at the time of inspection.	TOYO / YOKO DI
Bal. or Market Value: 976 K.	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal, 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm
Est. Repairs: days Res.: Yes or No	D.O.A. 29/11/2022 D.O.I. 07/12/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Yen Tee Synny
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S N/S / U/C / Rooftop or
Vehicle: IN / OL	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction	- The U/C / Chassis traine / Body Shuckare answer to the
Date / time Action / managed	•
13/12/22 Final fig \$1936.50 confirmed by en	nail (Red 4106, 67%)
1.	1
Date/Time, File Pass 10? : Preli. Report	Days Of Repair: 4 Resurvey No. of Trip: 1 Survey Fee:
1) Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
2) 13/12/22-typist Add	
2) 10/12/22-typist	: Interview (\$) Photos
Report Merimen	:Tech. Invs (\$) Others
Lump Sum / LB.A: (% \$1936.50	:Weekend (\$
	707.8

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No:200311009C)
Blk 6 Woodlands Road 399F., Yew Tee Ind Estate
Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

INSURER.

ECICS Limited (HO)

INSURER:	ECICS Limited (HQ)		
PARTICULARS OF CL	AIM		
Claim Type: Policy No: Vehicle Reg. No.:	OD (OWN DAMAGE) MPC22P00252700 SLH3410X	Ref. No: Date of Loss: Driveable?	29/11/2022 NO
Driver Age/Info: TP Injury Involved? Insured/Claimant:	46 / MALE YES AMELIA SHOO ENG LAN	Party At Fault: Third Party Involved?	NO UNKNOWN YES
Driver:	WONG JIN KAI		
Make/Model:	KIA SORENTO, 2.2 (A)	Vehicle Reg. Date:	31/10/2016
Vehicle Colour:	BROWN	Gen Condition:	GOOD
Engine No:	D4HBGH269654	Chassis No:	KNAPH81BMG5210081
Odometer:	85612 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	YEW TEE AUTOMOBILE TECH I	PTE LTD (HQ)	

COST OF CLAIMS		Amount
Parts		4,367.00
Miscellaneous Items		0.00
Labour		1,050.00
Paintwork Labour		565.00
Towing		0.00
	Gross Total (S\$)	5,982.00
	+ GST 7.00% (S\$)	418.74
	Nett Amount (S\$)	6,400.74

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 30 Nov 2022)

Parts:

M1-SUV

KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH3410X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*FRONT DOOR LH	0.00	0.00	*550.00 F
2	1 .	*FRONT DOOR HINGE TOP LH	0.00	0.00	*15.00 F B
3	1	*FRONT DOOR HINGE BOTTOM LH	0.00	0.00	*15.00 F b;
4	1	*FRONT DOOR LOWER PROTECTOR LH	0.00	0.00	*80.00 FM
5	1	*FRONT DOOR PILLAR LH	0.00	0.00	*1,450.00 F /C
6	1	*FRONT DOOR PILLAR INNER PANEL LH	0.00	0.00	*800.00 F R
7	1	*FRONT DOOR BOARD LH	0.00	0.00	*920.00 FX
8	1	*FRONT DOOR GLASS REGULATOR MOTOR LH	0.00	0.00	*70.00 F ?
9	1	*FRONT DOOR GLASS REGULATOR GEAR LH	0.00	0.00	*70.00 F 7
F=Fra	nchise part.				V
		Sub Total (S\$)			3,970.00
		+ Margin on L,N Items 10.00% (S\$)			397.00
		Total Parts (S\$)			4,367.00
		Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS			

nn nn nn

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type		Amount
Pair	ntwork Labour			
1	To Carry-Out Body Cavity Preservation.	New	1	20.00
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	400	500.00
3	To Supply Spray Terostat Sealant On The Cutting Areas.	New		45.00
Lab	our Items			_
4	To Transfer Door.	New	60	80.00
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New		30.00 ✓
6	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	600	900.00
7	To Reset Power Window.	New		40.00
	Gross Labou			1,615.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tarfilm 97495441 /67563561

Not Arthorise Exito be advise.

A Resum before perior 02/12/22 e 3/5 pm

+aufilm Clhhambon m

4-5deys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Nutroot Prejudice" basis
- Supplementary item(s) must be recurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: