

ASS. REC. BY: T. J. M.

REF:

CS/1052701.2015/Ty3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 100

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 970K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLH 3410X Yr Regn: 2016, Out

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Sorento C.C. 299

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 85612 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KWA RH 816M 95210081

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R: 1 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____ D.O.I. 02/12/22

Survey held at Sen Tee Syng

Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B.A. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI. _____

Photos _____

Others _____

TOTAL _____

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No:200311009C)

Blk 6 Woodlands Road 399F., Yew Tee Ind Estate

Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22P00252700	Date of Loss:	29/11/2022
Vehicle Reg. No.:	SLH3410X	Driveable?	NO
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	AMELIA SHOO ENG LAN		
Driver:	WONG JIN KAI		
Make/Model:	KIA SORENTO, 2.2 (A)	Vehicle Reg. Date:	31/10/2016
Vehicle Colour:	BROWN	Gen Condition:	GOOD
Engine No:	D4HBGH269654	Chassis No:	KNAPH81BMG5210081
Odometer:	85612 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	4,367.00
Miscellaneous Items	0.00
Labour	1,050.00
Paintwork Labour	565.00
Towing	0.00
Gross Total (S\$)	5,982.00
+ GST 7.00% (S\$)	418.74
Nett Amount (S\$)	6,400.74

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2022)

Parts: M1-SUV KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH3410X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR LH	0.00	0.00	*550.00 F <i>bt</i>
2	1		*FRONT DOOR HINGE TOP LH	0.00	0.00	*15.00 F <i>bt</i>
3	1		*FRONT DOOR HINGE BOTTOM LH	0.00	0.00	*15.00 F <i>bt</i>
4	1		*FRONT DOOR LOWER PROTECTOR LH	0.00	0.00	*80.00 F <i>mis</i>
5	1		*FRONT DOOR PILLAR LH	0.00	0.00	*1,450.00 F <i>Ry</i>
6	1		*FRONT DOOR PILLAR INNER PANEL LH	0.00	0.00	*800.00 F <i>Ry</i>
7	1		*FRONT DOOR BOARD LH	0.00	0.00	*920.00 F <i>X</i>
8	1		*FRONT DOOR GLASS REGULATOR MOTOR LH	0.00	0.00	*70.00 F <i>?</i>
9	1		*FRONT DOOR GLASS REGULATOR GEAR LH	0.00	0.00	*70.00 F <i>?</i>

F=Franchise part.

Sub Total (\$\$) 3,970.00
+ Margin on L,N Items 10.00% (\$\$) 397.00

Total Parts (\$\$) 4,367.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To Carry-Out Body Cavity Preservation.	New	20.00
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	400 500.00
3	To Supply Spray Terostat Sealant On The Cutting Areas.	New	45.00
<u>Labour Items</u>			
4	To Transfer Door.	New	80 80.00
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New	30.00
6	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	600 900.00
7	To Reset Power Window.	New	40.00
Gross Labour Cost (\$\$)			1,615.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97475741 / 67563561

Not Authorise Ex: to be advise.

Resurvey before print 02/12/22 03:15 pm

Taufik e1hantow
4-5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: