

## Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Blk 6 Woodlands Road 399F., Yew Tee Ind Estate

Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

INSURER:

ECICS Limited (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22P00252700	Date of Loss:	29/11/2022
Vehicle Reg. No.:	SLH3410X	Driveable?	NO
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	AMELIA SHOO ENG LAN		
Driver:	WONG JIN KAI		
Make/Model:	KIA SORENTO, 2.2 (A)	Vehicle Reg. Date:	31/10/2016
Vehicle Colour:	BROWN	Gen Condition:	GOOD
Engine No:	D4HBGH269654	Chassis No:	KNAPH81BMG5210081
Odometer:	85612 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (HQ)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	4,367.00
Miscellaneous Items	0.00
Labour	1,050.00
Paintwork Labour	565.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>5,982.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>418.74</b>
<b>Nett Amount (S\$)</b>	<b>6,400.74</b>

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 30 Nov 2022)  
**Parts:** M1-SUV      KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SLH3410X)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR LH	0.00	0.00	*550.00 F <i>bt</i>
2	1		*FRONT DOOR HINGE TOP LH	0.00	0.00	*15.00 F <i>bt</i>
3	1		*FRONT DOOR HINGE BOTTOM LH	0.00	0.00	*15.00 F <i>bt</i>
4	1		*FRONT DOOR LOWER PROTECTOR LH	0.00	0.00	*80.00 F <i>bt</i>
5	1		*FRONT DOOR PILLAR LH	0.00	0.00	*1,450.00 F <i>bt</i>
6	1		*FRONT DOOR PILLAR INNER PANEL LH	0.00	0.00	*800.00 F <i>bt</i>
7	1		*FRONT DOOR BOARD LH	0.00	0.00	*920.00 F <i>bt</i>
8	1		*FRONT DOOR GLASS REGULATOR MOTOR LH	0.00	0.00	*70.00 F <i>bt</i>
9	1		*FRONT DOOR GLASS REGULATOR GEAR LH	0.00	0.00	*70.00 F <i>bt</i>

F=Franchise part.

Sub Total (S\$)	3,970.00
+ Margin on L,N Items 10.00% (S\$)	397.00
<b>Total Parts (S\$)</b>	<b>4,367.00</b>

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

*- check bt - 15*  
*- quarter gearish de 40*  
*desing 9/12/22*  
*lyshi*

PARTS: \$715.00 + 10% = \$786.50

LABOUR : \$730.00

SPRAY : \$420.00

TOTAL \$1936.50

WE ALSO ATTACHED OUR SUPPLIER BILL FOR REF.

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To Carry-Out Body Cavity Preservation.	New	20.00
2	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	New	400 500.00
3	To Supply Spray Terostat Sealant On The Cutting Areas.	New	45.00
<u>Labour Items</u>			
4	To Transfer Door.	New	80 80.00
5	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	New	30.00
6	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	New	600 900.00
7	To Reset Power Window.	New	40.00
Gross Labour Cost (\$\$)			1,615.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Taufik 97475741 / 67563561  
Not Authorise Ex: to be advise.  
\* Resing before print 02/12/22 @ 3:15 pm  
taufik elhantaw  
4-5 days