

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012096/DNY3M4**Date:** 27/02/2023**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001833197

Claimant Vehicle No : SFP1972H**Insured Vehicle No :** FBG5612R

Date of Loss: 03/11/2022

Nature of Claim: TP

Claim No: 292611

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFP1972H**

Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)

Engine No: G4FGEU025697

Reg. Date: 16/10/2014 (Man. Year: 2014)

Chassis No: KMHDH41CMEU207910

Colour: White

Odometer: 108957 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Silverstone 5 mm

Rear Left Side: Silverstone 5 mm

Front Right Side: Silverstone 5 mm

Rear Right Side: Silverstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,049.12	486.20	20,562.92	97.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	400.00	5,220.00	92.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,669.12	886.20	25,782.92	96.68
Approved Total (Overridden) (S\$)		700.00		
(S\$)	26,669.12	700.00	25,969.12	97.38
+ GST 8.00/8.00% (S\$)	2,133.53	56.00	2,077.53	97.38
Nett Amount (S\$)	28,802.65	756.00	28,046.65	97.38

INSPECTION

Date of Assignment: 02/12/2022

Date Inspected: 06/12/2022 Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A, #03-08 AMK

AutoPoint

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFP1972H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,680.20 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	289.40 FL	*- FL
3	1		*BONNET SEAL	Not Necessary	89.00 FL	*- FL
4	1		*HEAD LAMP LH (CUT)	Not Consistent With The Impact	2,409.00 FL	*- FL
5	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	142.00 FL	*- FL
6	1		*HEAD LAMP ECU LH	Not Necessary	980.00 FL	*- FL
7	1		*HEAD LAMP WIRE HARNESS	Not Necessary	1,592.00 FL	*- FL
8	1		*FRONT BUMPER	Cut/Mtg Broken	589.00 FL	*589.00 FL
9	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	284.00 FL	*- FL
10	1		*FRONT BUMPER DAYTIME RUNNING LIGHTS LH	Not Necessary	401.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP HOLDER LH	Not Necessary	129.00 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,492.00 FL	*- FL
13	1		*FRONT BUMPER LOWER LID	Not Necessary	601.00 FL	*- FL
14	1		*FRONT BUMPER UNDER COVER	Not Necessary	410.00 FL	*- FL
15	2		*FRONT BUMPER SIDE RETAINER LH / RH @ \$65.00 EACH	Not Necessary	130.00 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Not Necessary	297.00 FL	*- FL
17	1		*FRONT REINFORCEMENT BAR	Not Necessary	982.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	1,829.00 FL	*- FL
19	1		*FRONT FENDER LH (DENTED)	Not Consistent With The Impact	890.00 FL	*- FL
20	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	159.00 FL	*- FL
21	1		*FRONT RIM LH	Repair	1,669.80 FL	*- FL
22	1		*FRONT WHEEL BEARING LH	Not Necessary	310.00 FL	*- FL
23	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	381.00 FL	*- FL
24	1		*FRONT KNUCKLE ARM LH	Not Necessary	795.00 FL	*- FL
25	1		*FRONT LOWER ARM LH	Not Necessary	490.00 FL	*- FL
26	1		*FRONT ABSORBER LH	Not Necessary	511.00 FL	*- FL
27	1		*FRONT STABILIZER LINK LH	Not Necessary	159.00 FL	*- FL
28	1		*FRONT STABILIZER BAR	Not Necessary	310.00 FL	*- FL
29	1		*FRONT TIE ROD LH	Not Necessary	210.00 FL	*- FL
30	1		*FRONT TIE ROD END LH	Not Necessary	341.00 FL	*- FL
31	1		*STEERING RACK & PINION ASSY	Not Necessary	2,890.00 FL	*- FL
32	1		*DRIVE SHAFT LH	Not Necessary	1,995.00 FL	*- FL
33	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
35	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*FRONT TYRE LH	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 26,136.40 604.00
- List Item Discount on L Items 20.00/20.00% (\$\$) 5,087.28 117.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	21,049.12 486.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	200.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,620.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >