

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/MSG22012099/AGVY3M4  
**Date:** 25/05/2023

**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001147931  
**Claimant Vehicle No :** SMY7499M **Insured Vehicle No :** GQ6996P  
Date of Loss: 19/11/2022 Nature of Claim: TP Claim No: 291841

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMY7499M**  
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGHU795820  
Reg. Date: 27/10/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU559884  
Colour: Silver Odometer: 148325 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm  
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,441.68	3,778.40	3,663.28	49.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,450.00	2,280.00	61.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,171.68</b>	<b>5,228.40</b>	<b>5,943.28</b>	<b>53.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,171.68</b>	<b>4,100.00</b>	<b>7,071.68</b>	<b>63.30</b>

**INSPECTION**

Date of Assignment: 02/12/2022  
Date Inspected: 05/12/2022 Inspected At: ADVANCE AUTO GARAGE  
23 KAKI BUKIT AVENUE 4,  
#04-01 VICOM KAKI BUKIT INSPECTION  
CENTER  
SINGAPORE 415933.  
Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2023)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMY7499M)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR	Dented	1,879.20 FL	*1,879.20 FL
2	1		*REAR DOOR LOCK	Damaged	265.40 FL	*265.40 FL
3	1		*RAR DOOR WEATHERSTRIPE	Not Necessary	159.40 FL	*- FL
4	1		*REAR DOOR OUTER HANDLE	Not Necessary	179.60 FL	*- FL
5	1		*REAR DOOR INNER TRIM BOARD	Not Necessary	658.20 FL	*- FL
6	1		*REAR FENDER	Dented	1,768.30 FL	*1,768.30 FL
7	1		*REAR BUMPER	Repair	481.40 FL	*- FL
8	1		*REAR BUMPER SIDE HOLDER	Not Necessary	38.90 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	135.10 FL	*135.10 FL
10	1		*REAR AXLE	Not Necessary	1,388.70 FL	*- FL
11	1		*REAR SHOCK ABSORBER	Not Necessary	230.50 FL	*- FL
12	1		*REAR WHEEL HUB C/W BEARING	Not Necessary	454.90 FL	*- FL
13	1		*SET REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
14	1		*REAR DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
15	1		*REAR DOOR DECORATIVE STICKER	Necessary	50.00 FS	*20.00 FS
16	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
17	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
18	1		*REAR WHEEL RIM	Cut	850.00 FS	*400.00 FS
19	1		*REAR TYRE	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,969.60</b>	<b>4,588.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,527.92	809.60
<b>Total Parts (S\$)</b>	<b>7,441.68</b>	<b>3,778.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,400.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	600.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR	New	100.00	0.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
7	TO TRANSFER DOOR FITTINGS	New	150.00	60.00
8	TO REMOVE REAR UNDERCARRIAGE	New	380.00	0.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,730.00</b>
				<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >