



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9848G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR TAILLAMPS	DAMAGED (1PC ONLY)	763.26	230.00
2	REAR MUDGUARDS -REAR	NOT NECESSARY	670.40	-
1	FRONT CABIN REAR PARTITION PANEL	TO REPAIR SEE LABOUR	1,865.80	-
1	AIR CLEANER INTAKE DUCT	DAMAGED	262.89	262.89
1	EGR COVER PIPE HOLE	DAMAGED	265.95	265.95
1	EGR PIPE EQUIP	SERVICEABLE	934.90	-
1	EGR PIPE COOLER WATER INLET	DAMAGED	188.77	188.77
1	EGR COVER GASKET	NECESSARY	192.21	192.21
	LESS 10% DISCOUNT		-514.42	-113.98
			4,629.76	1,025.84
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILGATE LOWER MEMBER - WOODEN (SN)	DAMAGED	1,000.00	500.00
1	REAR STEP PANEL -WOODEN (SN)	DAMAGED	600.00	350.00
1	REAR NUMBER PLATE (SN)	DAMAGED	50.00	35.00
2	REAR WOODEN CHASSIS PLANKS (SN)	DAMAGED	2,400.00	1,600.00
8	REAR WOODEN CHASSIS PLANK "U" BOLTS (SN)	NECESSARY	1,792.00	400.00
1	FRONT CANOPY BOARD (SN)	DAMAGED	1,500.00	500.00
2	REAR CANOPY TAILBOARD ASSY (SN)	TO REPAIR SEE LABOUR	2,800.00	-
1	O/S SIDE CANOPY BOARD (SN)	DAMAGED	1,500.00	500.00
			11,642.00	3,885.00
<u>LABOUR</u>				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT ENGINE PARTS.	NOT NECESSARY	250.00	-
	TO STRAIGHTEN REAR CHASSIS FRAME MEMBER AND RE-ALIGN CHASSIS FRAME.		1,200.00	500.00
	TO REMOVE, REFIX WHOLE CABIN TO ASSIST REPAIR.		800.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD ; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT CABIN REAR PARTITION PANEL AND REAR CANOPY TAILBOARD ASSY.		1,800.00	1,000.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,600.00	1,000.00
			5,730.00	3,030.00
GRAND TOTAL			22,001.76	7,940.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,350.00

Report Ref No. CS3/LPC22008267/Rvy3m4-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.