



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 9985G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	1,200.00	980.00
1	REAR BUMPER LOWER COVER	BROKEN	1,150.00	495.00
1	REAR BUMPER SPONGE	BROKEN	320.00	156.00
1	REAR BUMPER REINFORCEMENT	BUCKLED	720.00	550.00
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	85.00	-
1	REAR BUMPER CTR BRACKET	BROKEN	285.00	245.00
2	REAR BUMPER SIDE BRACKET @\$285.00	NOT NECESSARY	570.00	-
2	REAR BUMPER SIDE RETAINER @\$76.00	NOT NECESSARY	152.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
4	REVERSE SENSOR @\$260.00	NOT WORKING	1,040.00	740.00
1	REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	480.00	-
1	L/H EXHAUST CHROME	SERVICEABLE	550.00	-
1	TAILGATE	BROKEN	2,400.00	1,392.00
1	TAILGATE LOGO EMBLEM	NECESSARY	220.00	162.00
1	TAILGATE "RENAULT" EMBLEM	NECESSARY	180.00	145.00
1	TAILGATE "SPORT" EMBLEM	NECESSARY	180.00	145.00
1	TAILGATE "GT" EMBLEM	NECESSARY	120.00	120.00
1	TAILGATE INNER HANDLE SWITCH	NOT NECESSARY	175.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	280.00	-
1	TAILGATE INNER TRIM BOARD	NOT AFFECTED	700.00	-
10	REAR BOOT PAINTED CLIPS @\$15.00	NECESSARY	150.00	50.00
1	TAILGATE R/H LAMP	BROKEN	480.00	480.00
1	TAILGATE WEATHERSTRIP	DEFORMED	360.00	180.00
1	L/H TAILLAMP	NOT NECESSARY	580.00	-
1	R/H TAILLAMP	NOT NECESSARY	580.00	-
1	REAR END PANEL - OUTER	BUCKLED	850.00	850.00
1	REAR END PANEL - INNER	NOT NECESSARY	879.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	320.00	112.00
1	SPARE TYRE PANEL	BROKEN	1,800.00	883.00

Report Ref No. CS3/SMO22007353/Eqy3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-772.00
			16,841.00	6,948.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NO. PLATE (SN) }	BUCKLED	60.00	45.00
1	REAR NO. PLATE FRAME (SN) }	DEFORMED	35.00	-
			95.00	45.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.		1,600.00	800.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00
	TO REMOVE AND REINSTALL TAILGATE COMPONENTS.		80.00	60.00
	TO REMOVE AND REINSTALL REAR WINDSCREEN.		150.00	120.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.		120.00	80.00
	TO REMOVE AND REINSTALL REVERSE SENSOR.		140.00	40.00
	TO APPLY ANTI-RUST.		100.00	40.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		1,200.00	800.00
			3,450.00	1,970.00
	<b>GRAND TOTAL</b>		<b>20,386.00</b>	<b>8,963.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>7,100.00</b>

Report Ref No. CS3/SMO22007353/Eqy3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.