

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22012104/RPA3Q2**Date:** 20/03/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002819132
<b>Claimant Vehicle No :</b>	SNB3995H	<b>Insured Vehicle No :</b>	SMJ4834C
Date of Loss:	30/11/2022	Nature of Claim:	TP
		Claim No:	202222008569

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNB3995H</b>	Engine No:	B4204T317700741
Make & Model:	VOLVO XC40, 2.0 T4 R-DESIGN (A)	Chassis No:	LYVXZAKADML585891
Reg. Date:	19/08/2021 (Man. Year: 2021)	Odometer:	20833 km
Colour:	Grey		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,632.60	3,199.86	432.74	11.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,788.00	2,188.00	1,600.00	42.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,420.60</b>	<b>5,387.86</b>	<b>2,032.74</b>	<b>27.39</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>519.44</b>	<b>377.15</b>	<b>142.29</b>	<b>27.39</b>
<b>Nett Amount (S\$)</b>	<b>7,940.04</b>	<b>5,765.01</b>	<b>2,175.03</b>	<b>27.39</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		<b>300.00</b>		
	<b>Nett Liability (S\$)</b>	<b>6,065.01</b>		

INSPECTION

Date of Assignment:	02/12/2022	
Date Inspected:	13/12/2022	Inspected At: Wearnes Automotive Pte Ltd (alexandra) (HQ) 249 Alexandra Road Singapore 159103
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
<b>Parts:</b> M1-SUV	VOLVO XC40 2.0 T4 R-DESIGN (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNB3995H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*V039790879/BUMPER CO	Scratched	2,309.70 FS	*2,078.73 FS
2	1		*BUMPER SPOILER FRT A	Scratched	590.40 FS	*531.36 FS
3	1		*WHEEL AIR DEFLECTOR	Not Necessary	81.20 FS	*- FS
4	1		*WIDENER FRT RH XC40	Scratched	202.90 FS	*182.61 FS
5	1		*BUMPER INSTALLING MT	Necessary	101.40 FS	*91.26 FS
6	10		*BUMPER CLIP XC90 16	Necessary	88.00 FS	*79.20 FS
7	10		*BLIND RIVET 4.0*21 P	Necessary	50.00 FS	*46.80 FS
8	10		*BUMPER CLIP 8X8,5	Necessary	82.00 FS	*73.80 FS
9	10		*BUMPER CLIP GREEN S6	Necessary	60.00 FS	*54.00 FS
10	10		*EXPANDING NUT XC40 1	Necessary	67.00 FS	*62.10 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>3,632.60</b>	<b>3,199.86</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER ,FRONT LOWER BUMPER ,RHF FENDER WIDENER ,BRACKETS ,CLIPS ,ETC	New	1,700.00	850.00
2	TO BLEND AND SPRAY PAINT ON FRONT BUMPER ETC	New	1,500.00	750.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	588.00	588.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,188.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >