

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012111/UNP3Q2**Date:** 12/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00142782201		
Claimant Vehicle No :	SMC1371C	Insured Vehicle No :	SKA746X		
Date of Loss:	01/12/2022	Nature of Claim:	TP	Claim No:	SNM22D208656/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1371C	Engine No:	LEB6556834
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71213852
Reg. Date:	26/06/2018 (Man. Year: 2018)	Odometer:	48590 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,864.00	2,345.12	3,518.88	60.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,440.00	2,510.00	63.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,814.00	3,785.12	6,028.88	61.43
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	9,814.00	3,000.00	6,814.00	69.43
+ GST 7.00/7.00% (\$\$)	686.98	210.00	476.98	69.43
Nett Amount (\$\$)	10,500.98	3,210.00	7,290.98	69.43

INSPECTION

Date of Assignment:	08/12/2022		
Date Inspected:	05/12/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Dec 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC1371C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE GLASS MOULDING	Necessary	186.00 FL	*121.50 FL
2	1		*TAILGATE	Badly Dented	1,995.00 FL	*1,193.40 FL
3	1		*TAILGATE LOGO	Necessary	125.00 FL	*48.00 FL
4	1		*TAILGATE EMBLEM -SHUTTLE	Necessary	105.00 FL	*60.00 FL
5	1		*TAILGATE EMBLEM -HYUNDAI	Necessary	105.00 FL	*85.00 FL
6	1		*TAILGATE LOCK	Bent / Twisted	225.00 FL	*225.00 FL
7	1		*REAR BUMPER	Dented	1,380.00 FL	*936.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Not Necessary	104.00 FL	*- FL
9	1		*REAR END PANEL	Repair	860.00 FL	*- FL
10	1		*REAR END PANEL GARNISH	Not Necessary	285.00 FL	*- FL
11	1		*N/S REAR FENDER INNER TRIM	Not Necessary	955.00 FL	*- FL
12	1		*N/S REAR BUMPER REFLECTOR	Not Necessary	215.00 FL	*- FL
13	1		*N/S REAR BUMPER REFLECTOR GARNISH	Not Necessary	165.00 FL	*- FL
14	1		*TAILGATE GLASS INNER SEAL	Necessary	80.00 FS	*40.00 FS
15	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
17	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
18	1		*REAR BUMPER RIVET	Not Necessary	60.00 FS	*- FS
19	1		*REAR END PANEL GARNISH CLIP	Not Necessary	40.00 FS	*- FS
20	1		*N/S REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
21	1		*TAILGATE BODY SEALANT	Necessary	80.00 FS	*50.00 FS
22	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,205.00	2,878.90
- List Item Discount on L Items 20.00/20.00% (S\$)	1,341.00	533.78
Total Parts (S\$)	5,864.00	2,345.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO TRANSFER TAILGATE GLASS	New	120.00	120.00
3	TO TRANSFER TAILGATE MECHANISMS	New	120.00	60.00
4	TO FIT REVERSE SENSOR IN BUMPER	New	50.00	50.00
5	TO CONDUCT WATERTEST AT BOOT COMPARTMENT	New	50.00	0.00
6	TO RUSTPROOF ON DAMAGED PARTS	New	180.00	30.00
7	TO PUTTY AND RE-SPRAY ACCIDENT DAMAGE AREA	New	1,000.00	600.00
8	TO BARRICADE VEHICLE ,ENSURE SAFETY CHECK ,REMOVE SAFETY PLUG, DRAIN HYBRID BATTERY VOLTAGE ,ENSURE NO CURRENT BEFORE STARTING WORK ON THE VEHICLE	New	450.00	0.00
9	TO RECHARGE HYBRID BATTERY	New	350.00	0.00
10	TO DIAGNOSE AND RESET HYBRID SYSTEM USING DIAGNOSTIC SCANNER	New	380.00	60.00
11	TO REPAIR INNER PANEL ,ACCIDENT DAMAGE AREA ,CUT /REWELD REAR END PANEL ,REPLACEMENT OF PARTS AND ALIGN THE SAME	New	1,200.00	500.00
Gross Labour Cost (S\$)			3,950.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >