



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 8769J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	200.00	200.00
1	SUPPORT, FR BUMPER S (SN)	DAMAGED	101.70	101.70
1	COVER, FR BUMPER L/C (SN)	DEFORMED	633.80	633.80
1	FENDER SUB-ASSY, FR (SN)	BENT	1,081.20	1,081.20
1	LINER, FR FENDER, LH (SN)	DEFORMED	270.50	270.50
1	PANEL SUB-ASSY, QUAR (SN)	TO REPAIR SEE LABOUR	1,369.30	-
1	PANEL SUB-ASSY, FR D (SN)	BENT	1,495.20	1,495.20
1	TAPE, BLACK OUT, NO (SN)	NECESSARY	57.20	57.20
1	TAPE, BLACK OUT, NO (SN)	NECESSARY	51.90	51.90
1	PANEL SUB-ASSY, RR D (SN)	BENT	1,481.90	1,481.90
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	42.30	42.30
1	HUB & BRG ASSG, RR A (SN)	SERVICEABLE	1,143.90	-
2	WHEEL, DISC (SN)	SCRATCHED	4,781.60	4,781.60
1	SHAFT ASSY, FR DRIVE (SN)	SERVICEABLE	1,486.20	-
1	BEARING, RADIAL BALL (SN)	BENT	129.10	129.10
1	HUB SUB-ASSY, FR AXL (SN)	BENT	311.40	311.40
1	JOINT ASSY, LWR BALL (SN)	SERVICEABLE	283.60	-
1	KNUCKLE, STEERING, L (SN)	BENT	747.30	747.30
1	ARM SUB-ASSY, SUSPEN (SN)	SERVICEABLE	873.80	-
1	ABSORBER SET, SHOCK (SN)	BENT	523.40	523.40
1	HEADLAMP ASSY, LH (SN) (ADDITIONAL)	CRACKED	1,105.20	1,105.20
1	PROTECTOR, FR FENDER (SN) (ADDITIONAL)	DEFORMED	119.50	119.50
			18,390.00	13,183.20
	<u>LABOUR</u>			
	RESET ECU UPON COMPLETION OF REPAIR.		198.00	198.00
	CONDUCT WHEEL ALIGNMENT.		198.00	198.00
	REPL LH FRT UNDERCARRIAGE PART.		792.00	792.00
	REPL REAR LH UNDERCARRIAGE PART.		792.00	792.00
	TRANSFER FRT AND REAR TYRE TO NEW RIM.		160.00	160.00

Report Ref No. CS/SMR22012112/Rvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER RH FRT AND REAR DOOR MECHANISM.		792.00	792.00
	REPL ACC AFF PARTS AND PANEL. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, QUAR.		3,168.00	3,168.00
	RESPRAY ACC AFF AREA.		3,936.00	3,608.00
			10,036.00	9,708.00
GRAND TOTAL			28,426.00	22,891.20
RECOMMENDED COST OF REPAIRS				22,891.20

Report Ref No. CS/SMR22012112/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.