

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22012114/TYA3Q2**Date:** 08/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SMA365M **Insured Vehicle No :** GBJ1037L

Date of Loss: 30/11/2022 Nature of Claim: TP Claim No: MFL2022D0010822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA365M**
 Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25500638
 Reg. Date: 25/05/2018 (Man. Year: 2018) Chassis No: MRHFC5650JT000592
 Colour: Grey Odometer: 44651 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,880.29	7,824.74	2,055.55	20.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,170.00	14,411.50	6,758.50	31.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,050.29	22,236.24	8,814.05	28.39
+ GST 7.00/7.00% (S\$)	2,173.52	1,556.54	616.98	28.39
Nett Amount (S\$)	33,223.81	23,792.78	9,431.03	28.39
+ Car Rental (13.0 x S\$100.00/day + 7.00% GST) (S\$)		1,391.00		
Nett Liability (S\$)		25,183.78		

INSPECTION

Date of Assignment: 02/12/2022

Date Inspected: 05/12/2022 Inspected At: Kah Motor Co Sdn Bhd (HQ)
6A MANDAI ESTATE, SINGAPORE 729903
Singapore 729903

Estimated Period of Repair: 17.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA365M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD COMPENGINE	Bent	518.25 FS	*518.25 FS
2	1		*HINGE COMPR .HOOD	Bent	28.57 FS	*28.57 FS
3	1		*INSULATORHOOD	Not Necessary	66.60 FS	*- FS
4	1		*FACEFR BUMPER	Deformed	434.92 FS	*434.92 FS
5	1		*SPACERR.FR.BUMPER SIDE	Deformed	7.80 FS	*7.80 FS
6	1		*CLIP BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
7	1		*HEADLIGHT ASSY,R	Cracked	506.92 FS	*506.92 FS
8	1		*LIGHT ASSYR.SIDE TURN	Cut	50.62 FS	*50.62 FS
9	1		*MIRROR ASSY,R	Broken	220.12 FS	*220.12 FS
10	1		*CAP ,R.SKULL	Necessary	44.92 FS	*44.92 FS
11	1		*PANELR.FENDER	Bent	338.10 FS	*338.10 FS
12	1		*BRACKET AR.FR.FENDER	Bent	25.50 FS	*25.50 FS
13	1		*FENDERR.FR.INNER	Not Necessary	44.17 FS	*- FS
14	1		*PADR.FR.FENDER PARTITION	Not Necessary	38.17 FS	*- FS
15	1		*PANEL COMPR.FR.DOOR	Bent	678.82 FS	*678.82 FS
16	1		*HINGER.FR.DOOR UPPER	Not Necessary	33.22 FS	*- FS
17	1		*HINGER.FR.DOOR LOWER	Not Necessary	33.97 FS	*- FS
18	1		*CHECKER COMPFR DOOR	Not Necessary	11.70 FS	*- FS
19	1		*WEATHERSTRIP FR DOOR	Not Necessary	56.17 FS	*- FS
20	1		*SEALR.FR DOOR LOWER	Necessary	7.12 FS	*7.12 FS
21	1		*SEALR.FR DOOR FR .GAP	Not Necessary	10.87 FS	*- FS
22	1		*MOLDING ASSYR.FR.DOOR	Deformed	20.77 FS	*20.77 FS
23	1		*BASE COMPR FR	Cut	17.92 FS	*17.92 FS
24	1		*HANDLE COMPR	Cut	73.95 FS	*73.95 FS
25	1		*REGULATOR ASSYR.FR.DOOR	Serviceable	78.15 FS	*- FS
26	1		*SASHR .FR.DOOR CENTER LOWER	Not Necessary	7.12 FS	*- FS
27	1		*RUNCHANNEL ,R.FR.DOOR	Not Necessary	59.92 FS	*- FS
28	1		*PANELR.RR.DOOR	Bent	621.00 FS	*621.00 FS
29	1		*HINGER.RR.DOOR UPPER	Bent	32.85 FS	*32.85 FS
30	1		*HINGER.RR.DOOR LOWER	Not Necessary	33.22 FS	*- FS
31	1		*CHECKER COMP RR DOOR	Not Necessary	8.17 FS	*- FS
32	1		*WEATHERSTRIP ,R.RR.DOOR	Not Necessary	71.47 FS	*- FS
33	1		*SEALRR.DOOR LOWER	Necessary	5.32 FS	*5.32 FS
34	1		*MOLDING ASSYR.RR.DOOR	Deformed	21.82 FS	*21.82 FS
35	1		*REGULATOR ASSYR.RR.DOOR POWER	Not Necessary	95.10 FS	*- FS
36	1		*SASHR .RR.DOOR RR LOWER	Not Necessary	10.80 FS	*- FS
37	1		*RUN CHANNEL .R.RR.DOOR	Not Necessary	55.65 FS	*- FS
38	1		*GARNISH ASSY,R.SIDE SILL	Repair	101.92 FS	*- FS
39	1		*PANELR.FR.OUTSIDE	Bent	616.05 FS	*616.05 FS
40	1		*ADAPTERR.RR.COMBINATION LIGHT	Necessary	52.50 FS	*52.50 FS
41	1		*PANEL SETRR	Bent	210.52 FS	*210.52 FS
42	1		*STIFFENER,R.RR.PANEL SIDE	Necessary	23.10 FS	*23.10 FS
43	1		*PANELR.RR.INSIDE	Repair	183.52 FS	*- FS
44	1		*STIFFENER COMPR.RR.SHOCK ABSORBER	Serviceable	112.50 FS	*- FS
45	1		*EXTSN COMPR.RR.W/ARCH RFCMNT	Serviceable	32.10 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*WHEELHOUSE COMPR.RR	Repair	221.85 FS	*- FS
47	1		*SUPPORT COMPR.RR.SHELF	Repair	42.22 FS	*- FS
48	1		*FRAME COMPR.RR. FLOOR	Repair	557.10 FS	*- FS
49	1		*TAILLIGHT ASSYR	Cracked	226.27 FS	*226.27 FS
50	1		*TAILLIGHT ASSYL	Cracked	243.52 FS	*243.52 FS
51	1		*LIGHT ASSYR.LID	Cracked	105.82 FS	*105.82 FS
52	1		*LIGHT ASSYL.LID	Necessary	105.82 FS	*105.82 FS
53	1		*LID COMP TRUNK	Bent	543.52 FS	*543.52 FS
54	1		*HINGE COMPR.TRUNK	Bent	38.70 FS	*38.70 FS
55	1		*HINGE COMPL.TRUNK	Bent	38.70 FS	*38.70 FS
56	1		*GARNISH ASSYR.TRUNK HINGE	Deformed	13.35 FS	*13.35 FS
57	1		*LOCK ASSYTRUNK	Bent	64.35 FS	*64.35 FS
58	1		*WEATHERSTRIP TRUNK LID	Twisted	52.50 FS	*52.50 FS
59	1		*GARNISH ASSYRR.LICENSE	Deformed	87.07 FS	*87.07 FS
60	1		*EMBLEM .H-MARK	Necessary	10.57 FS	*10.57 FS
61	1		*NUT,PUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
62	1		*EMBLEM SETRR	Necessary	10.20 FS	*10.20 FS
63	1		*EMBLEMRR	Necessary	9.52 FS	*9.52 FS
64	1		*LINING ASSY,R.TRUNK	Deformed	42.22 FS	*42.22 FS
65	1		*FACE ASSY ,RR.BUMPER	Deformed	462.90 FS	*462.90 FS
66	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
67	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
68	1		*CLIP BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
69	1		*GARNISH,R.RR.BUMPER SIDE	Deformed	6.75 FS	*6.75 FS
70	1		*COVERR.FINISHER	Not Necessary	9.75 FS	*- FS
71	1		*REFLECTOR ASSYR.RR	Cracked	14.40 FS	*14.40 FS
72	1		*GARNISH ,RR.BUMPER LOWER	Not Necessary	31.50 FS	*- FS
73	1		*BEAM COMPRR BUMPER	Bent	142.57 FS	*142.57 FS
74	1		*DISKALUMINIUM WHEEL	Cut	360.00 FS	*360.00 FS
75	1		*RUBBER CWINDSHIELD DAM	Necessary	14.92 FS	*14.92 FS
76	3		*RUBBERRR QTR W/SHIELD	Necessary	23.40 FS	*23.40 FS
77	1		*FASTENER BW/SHIELD (2 PCS)	Necessary	7.95 FS	*7.95 FS
78	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
79	1		*CLIP,WINDSHIELD UPPER (2 PCS)	Necessary	5.25 FS	*5.25 FS
80	1		*RUBBER W/SHIELD	Necessary	10.65 FS	*10.65 FS
81	1		*RUBBER W/SHIELD	Necessary	12.15 FS	*12.15 FS
82	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
83	1		*GLASS ASSYR,QUARTER WINDSHIELD	Necessary	118.12 FS	*118.12 FS
84	1		*SUNDRIES	Necessary	100.00 FS	*60.00 FS
85	1		*LABEL AIR CON	Necessary	0.60 FS	*0.60 FS
86	1		*LABEL ,COOLANT INFORMATION	Necessary	8.62 FS	*8.62 FS
87	2		*CLIP ABUMPER	Necessary	3.90 FS	*3.90 FS
88	2		*GROMMET TAILLIGHT	Necessary	0.60 FS	*0.60 FS
89	1		*CLIP,TRIM ,7MM NH900L (2 PCS)	Necessary	4.65 FS	*4.65 FS
90	1		*CLIP ASSY ,TRIM (2 PCS)	Necessary	3.75 FS	*3.75 FS
91	1		*BRACKETR.RR.BUMPER SIDE	Necessary	1.87 FS	*1.87 FS
92	1		*SUB CORDRR BUMPER CORNER SENS	Necessary	24.30 FS	*24.30 FS
93	1		*GUTTERR.RR.UPPER	Necessary	25.50 FS	*25.50 FS
94	1		*OUTLET ASSY,RR.AIR	Necessary	7.05 FS	*7.05 FS
95	1		*MOLDING ASSYR.FR.DOOR SASH	Bent	22.95 FS	*22.95 FS
96	1		*GARNISH ASSYR.FR.DOOR SASH	Necessary	11.85 FS	*11.85 FS
97	1		*GARNISHR.FR.CENTER CORNER	Necessary	1.35 FS	*1.35 FS
98	1		*MOLDING ASSY,R.RR.DRINNER	Bent	42.97 FS	*42.97 FS
99	1		*GARNISH ASSYR.RR.DOOR SASH	Broken	21.22 FS	*21.22 FS
100	1		*GARNISHR .RR.CENTER CORNER	Necessary	1.20 FS	*1.20 FS
101	1		*LATCH ASSY ,R.FR .DOOR	Bent	79.72 FS	*79.72 FS

Report was unsubmitted during this print-out.

6/8/23, 10:19 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
102	1		*COVERR.FR.BASE	Necessary	2.02 FS	*2.02 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					9,880.29	7,824.74
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	180.00	162.00
2	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS	New	250.00	250.00
3	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	135.00
4	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	135.00
5	REMOVE & RENEW REVERSE SENSORS	New	180.00	135.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	585.00
7	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	450.00	292.50
8	REMOVE & TRANSFER ITEMS TO NEW FR R DR ADJUST	New	450.00	292.50
9	REMOVE & TRANSFER ITEMS TO NEW RR R DR ADJUST	New	450.00	292.50
10	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	292.50
11	REMOVE INSTALL CALIBRATE REAR VIEW CAMERA	New	450.00	292.50
12	REPLACE RR WINDSCREEN	New	650.00	585.00
13	REPLACE RR.R QTR GLASS	New	650.00	288.00
14	BODY JOINT SEALANT RHR FENDER	New	100.00	72.00
15	BODY JOINT SEALANT RHR QTR GLASS	New	100.00	72.00
16	BODY JOINT SEALANT TAILGATE	New	100.00	72.00
17	BODY JOINT SEALANT END PANEL	New	100.00	72.00
18	CUT & RENEW RR R FENDER STRAIGHTEN INNER PANEL	New	8,000.00	5,850.00
19	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (13[)	New	7,500.00	4,446.00
20	TOWING SERVICE (MBBS)	New	100.00	90.00
Gross Labour Cost (\$\$)			21,170.00	14,411.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >