

ESTIMATE OF REPAIR

Veh# : SLS421B

DOA : 3/12/2022

Location : WOODLANDS CENTRE ROAD

Model: NISSAN QASHQAI
5/9/2017

3P: SJM434U (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Regr. Revis</i>			1033.20
2	1 pc	Front bumper o/s retainer <i>new</i>			110.50
3	16 pcs	Front bumper clips <i>new</i>		80.00	
4	1 pc	Front o/s head lamp <i>new</i>			3895.80
5	1 pc	Front o/s fender <i>Regr.</i>			962.00
6	1 pc	Front o/s wheel arch garnish <i>at</i>			619.00
7	1 pc	Rear o/s wheel arch garnish <i>at</i>			619.00
8	12 pcs	O/s wheel arch garnish <i>clips. new</i>		60.00	
			0.00	80.00	6,620.50
			30%	0%	10%
		After Less %:	0.00	80.00	5958.45
		Labour			
1		To dismantle damaged parts, straighten & welding.	900.00	300	
2		To spray painting.	800.00	600	
3		To check fault code & re-set electrical system.	300.00	30	
4		To check wiring.	180.00	30	
5		To re-seal anti-rust.	100.00	60	
		Sub Total:		2,360.00	
		Total:		8,398.45	
		After Less 20%:		6,718.76	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SLS421B ESTIMATEPg1

Admin L
h/s 05/12/22

total: 2628.5

L/s: 2.1K.04Ry

2.1K