

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012124/UYA3Q2**Date:** 14/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100469460
Claimant Vehicle No :	SKT6170S	Insured Vehicle No :	SLD1500D
Date of Loss:	02/12/2022	Nature of Claim:	TP
		Claim No:	1200267454SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT6170S	Engine No:	P520287523
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Chassis No:	JM6BM42A8G0311630
Reg. Date:	17/06/2015 (Man. Year: 2015)	Odometer:	87680 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,385.80	6,495.98	5,889.82	47.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,970.00	3,510.00	3,460.00	49.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,355.80	10,005.98	9,349.82	48.31
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	19,355.80	8,000.00	11,355.80	58.67
+ GST 8.00/8.00% (S\$)	1,548.46	640.00	908.46	58.67
Nett Amount (S\$)	20,904.26	8,640.00	12,264.26	58.67
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,042.00		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment:	05/12/2022	
Date Inspected:	05/12/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Badly Dented	1,376.00 FL	*1,027.19 FL
2	1		*BOOT LID LOGO EMBLEM	Necessary	105.00 FL	*75.50 FL
3	1		*BOOT LID SKYACTIV EMBLEM	Necessary	99.00 FL	*68.00 FL
4	1		*BOOT LID MAZDA EMBLEM	Necessary	98.00 FL	*60.00 FL
5	1		*BOOT LID 3 EMBLEM	Necessary	78.00 FL	*45.00 FL
6	1		*BOOT LID INSULATOR	Deformed	246.00 FL	*246.00 FL
7	1		*BOOT LID HINGE	N/S Bent / O/S Not Necessary	486.00 FL	*165.00 FL
8	1		*BOOT LID LOCK	Twisted	264.00 FL	*164.00 FL
9	1		*BOOT LID WEATHERSTRIP	Twisted	185.00 FL	*185.00 FL
10	2		*REAR NUMBER PLATE LAMP	Not Necessary	236.00 FL	*- FL
11	1		*REAR BUMPER	Distorted	1,198.00 FL	*1,143.51 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	158.00 FL	*79.00 FL
13	1		*BOOT LID TOW HOOK COVER	N/S Torn	136.00 FL	*16.50 FL
14	1		*N/S REAR BUMPER REFLECTOR	Broken	92.00 FL	*53.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Distorted	859.00 FL	*564.20 FL
16	1		*REAR END PANEL	Badly Dented	890.00 FL	*542.97 FL
17	1		*REAR END PANEL GARNISH	Twisted	148.00 FL	*148.00 FL
18	1		*N/S BOOT LID GUTTER PANEL	Badly Dented	355.00 FL	*211.00 FL
19	1		*N/S TAILLAMP	Broken	898.00 FL	*546.93 FL
20	1		*N/S TAILLAMP PANEL	Badly Dented	350.00 FL	*245.00 FL
21	1		*N/S TAILLAMP SPONGE	Necessary	60.00 FL	*18.00 FL
22	1		*N/S REAR FENDER	Badly Dented / Buckled	1,742.00 FL	*1,262.77 FL
23	1		*N/S REAR FENDER INNER SHIELD	Torn	184.00 FL	*102.30 FL
24	1		*N/S REAR FENDER AIR DUCT	Twisted	98.00 FL	*75.50 FL
25	1		*N/S REAR FENDER INNER TRIM	Torn	397.00 FL	*282.60 FL
26	1		*REAR WINDSCREEN MOULDING	Necessary	128.00 FL	*80.50 FL
27	1		*SPARE TYRE PANEL	Repair	987.00 FL	*- FL
28	1		*FUEL TANK FLAP	Not Necessary	298.00 FL	*- FL
29	1		*BOOT LID SEALANT	Necessary	100.00 FS	*50.00 FS
30	1		*BOOT LID INSULATOR CLIP (12 PCS)	Necessary	60.00 FS	*50.00 FS
31	1		*BOOT LID LAMP	N/S Broken	760.00 FS	*220.00 FS
32	1		*REAR NUMBER PLATE	Bent	45.00 FS	*40.00 FS
33	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
34	1		*REAR BUMPER CLIP (12 PCS)	Necessary	60.00 FS	*50.00 FS
35	12		*REAR BUMPER RIVET	Not Necessary	60.00 FS	*- FS
36	1		*SET REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
37	10		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
38	4		*N/S TAILLAMP CLIPS	Not Necessary	20.00 FS	*- FS
39	12		*N/S REAR FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
40	1		*N/S REAR FENDER INNER TRIM CLIPS (12 PCS)	Necessary	60.00 FS	*50.00 FS
41	1		*REAR WINDSCREEN INNER SEAL	Necessary	100.00 FS	*40.00 FS
42	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
43	1		*SPARE TYRE PANEL INSULATOR RUBBER	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,816.00	7,977.47
- List Item Discount on L Items 20.00/20.00% (\$)	2,430.20	1,481.49
Total Parts (\$)	12,385.80	6,495.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	30.00
2	APPLY BODY SEALANT TO CAR JOINTS	New	150.00	50.00
3	RESPRAY ANTI RUST	New	150.00	90.00
4	TO TRANSFER REAR WINDSCREEN GLASS	New	150.00	120.00
5	TRANSFER BOOT LID PARTS	New	120.00	60.00
6	INSTALL REVERSE SENSOR }	New	100.00	50.00
7	INSTALL REVERSE CAMERA }	New	150.00	0.00
8	TO REMOVE INNER TRIM GARNISH ,SEAT ,SPEAKER BOARD ,ROOF LINNING AND ETC TO FACILITATE REPAIRS AND FIX BA	New	250.00	100.00
9	TO REMOVE N/S CURTAIN AIR BAG TO FACILITATE REPAIRS AND TO FIX BACK	New	250.00	0.00
10	TO USE DIAGNOSTIC SCANNER TO CLEAR SRS FAULT CODE	New	200.00	50.00
11	TO DROP FUEL TANK TO FACILITATE REPAIRS AND TO FIX BACK	New	300.00	60.00
12	TO DROP REAR UNDERCARRIAGE PARTS TO FACILITATE REPAIRS AND TO FIX BACK	New	300.00	0.00
13	TO CONDUCT CHASSIS ALIGNMENT	New	400.00	0.00
14	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL ,REPAIR INNER PANEL ,REWELD INNER PANEL,REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	2,200.00	1,500.00
15	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	2,200.00	1,400.00
Gross Labour Cost (S\$)			6,970.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >