

SMZ9183E.

Nissan GTR.

R35004363.

TPAXA

Dec 2022

Xiao Tony.

6500 (SN)

Front Bumper

Cracked

~~10000 (SN)~~

4500 (SN)

Front Bumper lower Spoiler (Carbon Fibre).

Cracked.

~~8000 (SN)~~

~~Front Bumper Centre Grille (Carbon Fibre)~~

=

Front Bumper Reinforcement.

None

2650.

Front Bumper Side Signal Lamp RH.

None

300 (SN) +

Front Bumper Side Signal Lamp Cover RH.

None

480 (SN) +

Headlamp RH. Cracked

3950

List: 3950

S.N 11000

Len 10%: 3555

SMZ9183E.

Panel Beating
Spray Painting.
Wiring.

~~500~~ 250
~~500~~ 250
530
~~50~~ 30

Total: 15085

L/S: 12K...

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~42~~

\$12,000

3 days