

(08/11/13) wef

ASS. REC. BY:

REF:

CC4/ASM 22012132/Dpa³

ASSIGNMENT

COR March 2023

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJD 5867T Yr Regn: 2008 / MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Vios c.c. 1497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 226186 T/Radio: Insured / Std / NI / NAEng/No: 2 2N2X703481C/No: M R053HY9305050678Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front _____ Rear _____

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 01/12/2022 D.O.I. 07/12/2022Survey held at Goh Lee Twa AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AXA SLC 9325X</u>
	<u>MV 3.8K</u> <u>Vehicle badance about 3 mths. plus</u>
	<u>LTA 1.2K</u> <u>using average depreciation of about 11K per year</u>
	<u>HL 2.6K</u>
<u>21/12/2022</u>	<u>Invoice 2,600/- with 5 days of delay</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

Reference No: 21222**[WITHOUT PREJUDICE SAVE AS TO COSTS]****Date: 2.12.2022****Cheong Limousine****231 Serangoon Ave 3 #02-44****Singapore 550237.****Toyota Vios 1.5****Estimated Repair Cost for Vehicle Reg. No: SJD 5867 T****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Front Bonnet <i>BT</i>	599.80	✓
1 Pc. Front Bonnet Lock <i>HH</i>	187.60	X
1 Pc. Front RH Fender <i>Blue</i>	395.50	✓
1 Pc. Front RH Fender Retainer <i>BT</i>	148.00	✓
1 Pc. Front RH Fender Dust Garnish <i>damaged</i>	205.00	✓
10 Pcs. Front Dust Garnish Clips <i>HH</i> @ 6.00	60.00	✓ 15/- SH
1 Pc. Front Fender Corner Cover <i>mostly broken</i>	98.00	✓
2 Pcs. Front Head Lamp Assy. <i>O/S broken H/S HH</i> @ 498.00	996.00	✓
1 Pc. Front Head Lamp Bulb <i>HH</i>	50.00	X
2 Pcs. Front Signal Lamp Bulb <i>HH</i> @ 10.00	20.00	X
1 Pc. Front Bumper <i>Dented / broken</i>	590.00	✓
1 Pc. Front Bumper Beam <i>HH</i>	239.60	X
2 PCs. Front Bumper Holder <i>HH</i> @ 80.00	160.00	X
1 Pc. Front Bumper Logo <i>HH</i>	80.00	✓
1 Pc. Front Bumper Lower Grille <i>HH</i>	225.00	X
1 Pc. Front Fog Lamp Assy. <i>HH</i>	298.30	X
1 Pc. Front Fog Lamp Cover <i>damaged</i>	103.00	✓
1 Pc. Front Towing Cover <i>damaged HH</i>	80.00	X
1 Pc. Front Lower Lip <i>broken</i>	499.00	✓
2 Pcs. Support Beam <i>O/S BT H/S HH</i> @ 92.00	184.00	✓
1 Pc. Support Panel <i>HH</i>	596.80	X
8 Pcs. Lower Lip Clips <i>HH</i> @ 6.00	48.00	15/- SH
1 Pc. Radiator <i>HH</i>	799.60	X
1 Pc. Air-con Condenser <i>HH</i>	598.00	X

*1 Pc Rocker Panel garnish**499.80 ✓*

Page 1 of 3

*HH**White*

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Front RH Absorber HH	298.50 X
1 Pc. Front RH Absorber Mounting HH	196.30 X
1 Pc. Front RH Knuckle Arm HH	399.80 X
1 pc. Front RH Wheel Hup HH	310.00 X
1 {c. Front RH Wheel Bearing HH	210.00 X
1 Pc. Front RH Steering Tie Rod HH	198.00 X
1 Pc. Front RH Steering Tie Rod End HH	120.00 X

Total (Panels / Parts): 8,993.80 (SGD)

list 25%

3808.10

SH

30.00%

25% 2856.07

LABOR CHARGES

To check wiring & remove all lighting.	120.00 30/-
To check & adjust computer wheel alignment.	120.00 60/-
To remove & refit undercarriage damaged parts & renew.	500.00 HH
To remove & refit air-con condenser, radiator & top-up Gas & oil.	180.00 HH
To knocking, straightening repair & renew all accident damaged affected area.	1,200.00 700/-
To respray painting on all accident affected area.	1,200.00 700/-
To rust proof all accident affected area.	120.00 60/-

1550.00%

Total (Labor Charges): 3,440.00 (SGD)

using depreciation of about 11k/yr.

value before 3 months.

MV about 3k.

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

TOTAL COST SUMMARY

PANELS / PARTS	8,993.80
LABOR CHARGES	3,440.00

Grand Total: 12,433.80 (SGD)

For payment.

1. PAYNOW: UEN 200808259H

2. BANK TRANSFER: Maybank Singapore Acct. No. 04141090974

ACKNOWLEDGED BY	DATE	GOH LEE HWA AUTOMOBILE PTE LTD
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

07/12/2022 @ 1000m
HWA Autos

2/5m

R
Ryan

JKK Autos

4436.07

R/S 2,600/-

5 days

Repair limit 2.5k

Plus after 2.5k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: