

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22012136/UYA3Q2**Date:** 18/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220006136
<b>Claimant Vehicle No :</b>	SND3559Z	<b>Insured Vehicle No :</b>	SMP7337U
Date of Loss:	05/12/2022	Nature of Claim:	TP
		Claim No:	5486109992SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SND3559Z</b>	Engine No:	L15B6020596
Make & Model:	HONDA SHUTTLE, 1.5 G CVT SENSING (A)	Chassis No:	GK82100492
Reg. Date:	23/12/2021 (Man. Year: 2019)	Odometer:	24067 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,467.36	1,481.04	986.32	39.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,660.00	520.00	23.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,647.36</b>	<b>3,141.04</b>	<b>1,506.32</b>	<b>32.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	4,647.36	2,500.00	2,147.36	46.21
<b>+ GST 7.00/7.00% (S\$)</b>	325.32	175.00	150.32	46.21
<b>Nett Amount (S\$)</b>	<b>4,972.68</b>	<b>2,675.00</b>	<b>2,297.68</b>	<b>46.21</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>(S\$)</b>		2,975.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,487.50</b>		

**INSPECTION**

Date of Assignment:	13/12/2022		
Date Inspected:	13/12/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Badly Dented	877.00 FL	*877.00 FL
2	1		*FRT RH DOOR POWER WINDOW REGULATOR	Not Necessary	418.10 FL	*- FL
3	1		*FRT RH DOOR POWER WINDOW REGULATOR MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*FRT RH DOOR KEY LOCK	Cut	140.30 FL	*140.30 FL
5	1		*REAR RH DOOR	Repair	814.80 FL	*- FL
6	1		*FRT RH DOOR HANDLE -OUTER	Cut	382.90 FL	*382.90 FL
7	1		*RH SIDE SKIRT	Torn	451.10 FL	*451.10 FL
8	1		*RH ROCKER PANEL (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,084.20	1,851.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	616.84	370.26
Total Parts (\$\$)	2,467.36	1,481.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING	New	1,000.00	980.00
2	LABOUR CHARGE	New	980.00	580.00
3	WIRING ,REMOVE AND REFIG DOOR GEARS	New	120.00	60.00
4	TUFF COAT	New	80.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,180.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >