

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS22012142/KQY3M4**Date:** 26/04/2023**REFERENCE**

Insured/Claimant:	BIS MOTORING PTE LTD	Policy No:	SP2002451400
Date of Loss:	01/12/2022	Nature of Claim:	OD
		Claim No:	202222008576

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9917E		
Make & Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 (A)	Engine No:	A2172908GKCX0153
Reg. Date:	08/01/2019 (Man. Year: 2017)	Chassis No:	W0VZM6EF6J1068736
Colour:	Black	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,730.82	6,623.32	3,107.50	31.93
Miscellaneous Items	119.00	119.00	0.00	0.00
Labour	2,120.00	1,180.00	940.00	44.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,969.82	7,922.32	4,047.50	33.81
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	9,969.82	5,922.32	4,047.50	40.60
+ GST 7.00/8.00% (S\$)	697.89	473.79	224.10	32.11
Nett Amount (S\$)	10,667.71	6,396.11	4,271.60	40.04

INSPECTION

Date of Assignment:	03/12/2022	Present Location:	Munich Autocare Pte Ltd (HQ)
Date Inspected:	09/12/2022	Inspected At:	Munich Autocare Pte Ltd (HQ) 60 Jalan Lam Huat, #07-43 Carros Center Singapore 737869
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2023)
Parts: 143	OPEL INSIGNIA GRANDSPORT B16DTH 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG9917E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	39214206	*FRONT BONNET (WCP)	Bent	1,705.00 F	*1,705.00 F
2	1	39107929	*FRONT RADIATOR GRILLE (WCP)	Serviceable	299.00 F	*- F
3	1	13491196	*FRONT RADIATOR GRILLE MOULDING (CHROME) (WCP)	Serviceable	274.00 F	*- F
4	1	13491204	*FRONT LOGO EMBLEM (WCP)	Serviceable	75.00 F	*- F
5	1	39159651	*FRONT BUMPER (WCP)	Buckled/Cracked	1,158.00 F	*1,158.00 F
6	1	39098178	*FRONT BUMPER SPONGE (WCP)	Serviceable	107.00 F	*- F
7	1	13460223	*FRONT FOGLAMP LH (WCP)	Serviceable	253.00 F	*- F
8	1	39138751	*FRONT FOGLAMP COVER LH (WCP)	Serviceable	145.00 F	*- F
9	1	13491269	*INSERT, CHROME, FRONT FOGLAMP LH (WCP)	Serviceable	537.00 F	*- F
10	1	39210099	*FRONT HEADLAMP LH (WCP)	Broken	1,161.00 F	*1,161.00 F
11	1	13491381	*HEADLAMP BRACKET LH (WCP)	Cracked	47.00 F	*47.00 F
12	2	95515167	*FRONT PARKING SENSOR (WCP)	Missing	410.00 F	*820.00 F
13	1		*FRONT BUMPER WIRING HARDNESS (WCP)	Serviceable	323.00 F	*- F
14	1	39108782	*FRONT PEDESTRIAN CRASH SENSOR (WCP)	Serviceable	342.00 F	*- F
15	1	39125439	*FRONT FENDER LH (WCP)	Bent	597.00 F	*597.00 F
16	1		*FRONT FENDER INNER SHIELD OUTER (WCP)	Cracked	220.00 F	*220.00 F
17	1	13312747	*Tyre rim - Alloy Rim (WCP)	Serviceable	458.00 F	*- F
18	1	39209192	*Headlamp Control Module LH (WCP)	Serviceable	422.00 F	*- F
Supplementary #1						
19	1	39209192	*H/LAMP CONTROL UNIT (WCP)	Shorted	270.00 F	*270.00 F
20	1	YR00274980	*LH GUIDE (WCP)	Cracked	28.00 F	*28.00 F
21	1	39112563	*LH ENERRY ABSORBER (WCP)	Cracked	15.20 F	*15.20 F

F=Franchise part.

Sub Total (\$\$)	8,846.20	6,021.20
+ Margin on L,N Items 10.00/10.00% (\$\$)	884.62	602.12
Total Parts (\$\$)	9,730.82	6,623.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	7	BUMPER CLIP (Necessary)	49.00	49.00
2	10	FENDER INNERSHIELD CLIP SET (Necessary)	70.00	70.00
Sub Total (\$\$)			119.00	119.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, AND ALL THE EFFECRED AREA.	New	1,000.00	500.00
2	TO DISMANTLE & RENEW FRONT PARKING SENSOR	New	120.00	60.00
3	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION INCLUDING ADJUST OF HEADLAMP	New	120.00	20.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	80.00	0.00
5	TO RESPRAY FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH ,AND ALL THE EFFECTED AREA	New	800.00	600.00
Gross Labour Cost (\$\$)			2,120.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >