



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 8261P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN	CRACKED	5,000.00	4,800.00
1	WIPER LINK	BENT	680.00	680.00
1	SET WIPER ARM	SCRATCHED	770.00	480.00
1	SET WIPER BLADE	NECESSARY	210.00	185.00
1	SET REAR VIEW MIRROR (L & R)	CRACKED	3,200.00	3,200.00
1	FRONT GRILLE	CRACKED	385.00	385.00
	LESS 10% DISCOUNT		-	-973.00
			10,245.00	8,757.00
	<u>SPECIAL NETT ITEMS</u>			
1	ERP BRACKET (SN)	NECESSARY	26.00	26.00
8	TUBES SEALANT (SN)	NECESSARY	320.00	200.00
			346.00	226.00
	<u>LABOUR</u>			
	LABOUR CHARGES FOR DISMANTLE & ASSEMBLE FRONT WINDSCREEN.		1,150.00	500.00
	LABOUR CHARGES FOR REMOVE & REPLACE THE ABOVE DAMAGED PARTS, CHECKING ALIGNMENT.		2,800.00	600.00
	TO PUTTY & SPRAY PAINTING ONTO AFFECTED AREAS.		1,500.00	600.00
	WIRING CHARGES.	NOT NECESSARY	160.00	-
			5,610.00	1,700.00
	GRAND TOTAL		16,201.00	10,683.00
	RECOMMENDED COST OF REPAIRS			10,683.00

Report Ref No. CS/FCI22012157/Rny3m4

MARKET VALUE: \$110,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$.00=NETT VALUE: \$110,000.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.