



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22012157/Rny3m4 Date: 16/01/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMB 3512E	Veh. Inspected	CB 8261P
Policy No.		Coverage (\$)	0.00
Claim No.	D22003825MFBP	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	05/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YUTONG ZK6107H	c.c	6693
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	LZYTBD6XB1014495	Colour	GREY
Odometer	584631 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	11R22.5	LING LONG	8 mm
L/H Front Tyre	11R22.5	LING LONG	8 mm
R/H Rear Tyre	11R22.5 (D/D)	LING LONG	8/8 mm
L/H Rear Tyre	11R22.5 (D/D)	LING LONG	8/8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	30/11/2022	Inspection Date	07/12/2022
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	