



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 7011D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	875.20	533.90
1	FRONT BUMPER SIDE RETAINER - LH	CRACKED	75.00	75.00
1	FRONT BUMPER SIDE RETAINER - RH	SERVICEABLE	75.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER SPONGE	SERVICEABLE	198.50	-
1	FOG LAMP - LH	SERVICEABLE	454.20	-
1	FOG LAMP - RH	SERVICEABLE	454.20	-
1	FOG LAMP GARNISH - LH	SERVICEABLE	252.00	-
1	HEAD LAMP - LH	MTG CRACKED	1,274.12	656.30
1	FRONT FENDER - LH	BENT	852.60	509.10
1	FRONT FENDER DUST COVER - LH	SERVICEABLE	225.00	-
1	SET FRONT FENDER DUST COVER CLIP - LH	NOT NECESSARY	50.00	-
	LESS 25% DISCOUNT		-	-456.08
			4,835.82	1,368.22
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL RIM - LH (SN)	DENTED	600.00	320.00
			600.00	320.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.		1,000.00	400.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,000.00	400.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		150.00	30.00
	TO CHECK WIRING FUNCTIONS.		80.00	15.00
			2,230.00	845.00
	GRAND TOTAL		7,665.82	2,533.22

Report Ref No. CS/FCI22012159/Kny3m4



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00
---	--	--	-----------------

Report Ref No. CS/FCI22012159/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.