

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012161/UQY3Q2**Date:** 23/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00016992201

Claimant Vehicle No : SNG7686Y**Insured Vehicle No :** PC2931U

Date of Loss: 04/12/2022

Nature of Claim: TP

Claim No: SNM22D208710/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNG7686Y**

Make & Model: MERCEDES-BENZ GLE400, 3.0 4MATIC (A)

Engine No: 27682130236713

Reg. Date: 10/05/2016 (Man. Year: 2015)

Chassis No: WDC1660562A620537

Colour: Silver

Odometer: 89706 km

Engine Capacity: 2996 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/45 R20

Rear Tyre Size: 265/45 R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,857.05	6,428.33	11,428.72	64.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	1,370.00	3,190.00	69.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,417.05	7,798.33	14,618.72	65.21
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	22,417.05	6,200.00	16,217.05	72.34

INSPECTION

Date of Assignment: 07/12/2022

Date Inspected: 06/12/2022 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)
25 Kaki Bukit Road 4, #01-49 Synergy@KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLE400 3.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG7686Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	185.00 FL	*- FL
2	1		*REAR TAILGATE	Repair	2,907.90 FL	*- FL
3	1		*REAR TAILGATE INNER BOARD	Not Necessary	226.50 FL	*- FL
4	2		*REAR TAILGATE LAMPS	Not Necessary	1,026.20 FL	*- FL
5	1		*REAR TAILGATE INNER LOCK	Not Necessary	290.80 FL	*- FL
6	1		*REAR TAILGATE LOGO	Necessary	68.50 FL	*68.50 FL
7	1		*REAR TAILGATE GLE400 EMBLEM	Necessary	88.50 FL	*88.50 FL
8	1		*REAR TAILGATE MATIC EMBLEM	Necessary	85.00 FL	*85.00 FL
9	1		*REAR TAILGATE OUTER CHROME GARNISH	Not Necessary	143.50 FL	*- FL
10	2		*REAR TAILLAMPS	Not Necessary	2,266.00 FL	*- FL
11	1		*REAR END PANEL	Repair	916.85 FL	*- FL
12	1		*REAR BUMPER INNER RETAINER	Twisted	289.70 FL	*289.70 FL
13	1		*REAR BUMPER	Distorted	2,556.90 FL	*2,556.90 FL
14	1		*REAR BUMPER LOWER DIFFUSER	Distorted	825.50 FL	*655.00 FL
15	2		*REAR BUMPER REFLECTORS	Scratched / Cracked	190.40 FL	*190.40 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	554.40 FL	*554.40 FL
17	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	68.00 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Cracked	170.00 FL	*170.00 FL
19	6		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,878.00 FL	*564.00 FL
20	1		*REAR BUMPER LOWER MOULDING	Cracked	528.00 FL	*528.00 FL
21	2		*REAR EXHAUST CHROME TAIL PIPES	Scratched / Bent	548.40 FL	*548.40 FL
22	1		*REAR PDC SENSOR WIRE	Torn	1,950.00 FL	*366.01 FL
23	2		*REAR EXHAUST MOUNTINGS	Not Necessary	96.00 FL	*- FL
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
26	1		*REAR BUMPER TOP STEP CHROME	Cracked	380.00 FS	*380.00 FS
27	1		*REAR FLOOR MAT	Not Necessary	300.00 FS	*- FS
28	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,750.05	7,094.81
- List Item Discount on L Items 5.00/10.00% (\$\$)	893.00	666.48
Total Parts (\$\$)	17,857.05	6,428.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	200.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO APPLY UNDERCOATING	New	200.00	0.00
7	PANEL BEATING	New	1,600.00	600.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	600.00
9	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	500.00	100.00
Gross Labour Cost (S\$)			4,560.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >