

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012169/TVP3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00078762201
Claimant Vehicle No :	SJP2598B	Insured Vehicle No :	YQ987S
Date of Loss:	05/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208703/C03/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP2598B	Engine No:	A7520880N20B20A
Make & Model:	BMW 528i, 2.0 AT ABS D/AB SR NAV HID (A)	Chassis No:	WBA5A52010D823541
Reg. Date:	13/05/2015 (Man. Year: 2014)	Odometer:	53783 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,847.24	7,356.49	2,490.75	25.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,183.00	13,256.00	927.00	6.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,030.24	20,612.49	3,417.75	14.22
+ GST 8.00/8.00% (S\$)	1,922.42	1,649.00	273.42	14.22
Nett Amount (S\$)	25,952.66	22,261.49	3,691.17	14.22

INSPECTION

Date of Assignment:	05/12/2022	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Date Inspected:	20/02/2023 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	143	BMW 528i 2.0 AT ABS D/AB SR NAV HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP2598B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS
3	10		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	8.50 FS	*- FS
4	1		*EXTENSION FOR REAR LH WHEEL	Not Necessary	1,099.10 FS	*- FS
5	1		*RR LH FENDER	Buckled	2,232.65 FS	*2,232.65 FS
6	1		*REINFORCEMENT PLATE C PILLAR LH	Not Necessary	54.80 FS	*- FS
7	1		*REINFORCEMENT PLATE ROCKER PANEL LH	Not Necessary	54.80 FS	*- FS
8	10		*T WELD BOLT L=5.4MM	Obstructed	9.00 FS	*- FS
9	1		*RR LH MOUNT	Cracked	205.70 FS	*205.70 FS
10	1		*RR RH MOUNT	Deformed	205.70 FS	*205.70 FS
11	1		*REAR BUMPER PRIMED (PDC)	Torn	1,616.00 FS	*1,616.00 FS
12	1		*RR WINDOW GREEN	Necessary	909.10 FS	*909.10 FS
13	1		*RR LH LIGHT IN THE SIDE PANE	Cracked	657.15 FS	*657.15 FS
14	1		*BLIND RIVET AVIBVLB (50 PCS)	Necessary	27.50 FS	*27.50 FS
15	5		*SCREW (SF PLUS M5X15)	Necessary (3 PCS ONLY)	3.00 FS	*1.80 FS
16	20		*PUNCH RIVET N5	Not Necessary	11.00 FS	*- FS
17	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	125.60 FS	*125.60 FS
18	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
19	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
20	1		*PUNCH RIVET N4 (50 PCS)	Necessary	27.50 FS	*27.50 FS
21	1		*(DG/SL) BODY ADHESIVE K5 (195ML)	Necessary	364.15 FS	*364.15 FS
22	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
23	3		*(SL/DG) SEALANT D2 290ML	Necessary (1 PCS ONLY)	96.30 FS	*32.10 FS
24	1		*EXPANDING NUT	Necessary	0.65 FS	*0.65 FS
25	1		*3M S/F PRIMIUM REAR WINDSCREEN	Necessary	252.34 FS	*252.34 FS
26	10		*BUMP STOP	Necessary	34.50 FS	*34.50 FS
27	1		*CLIP BOTTOM PART	Necessary	1.65 FS	*1.65 FS
28	1		*REAR LH WHEEL HOUSING COVER	Deformed	169.15 FS	*169.15 FS
29	1		*RR LH LIGHT IN THE SIDE PANEL	Repeated	657.15 FS	*- FS
30	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,847.24 7,356.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
2	TO REPLACE REAR BUMPER ,LEFT REAR FENDER ,LEFT TRUNK FLOOR PANEL INCLUDING TO PULL & STRAIGHTEN REAR LEFT FENDER BEFORE CUTTING AND TO KNOCK OUT DENTED AREA	New	5,950.00	5,100.00
3	TO RESPRAY REAR BUMPER ,LEFT REAR FENDER ,LEFT ROOF FRAME ,TAIL PANEL AND BOOT COMPARTMENT	New	6,074.00	6,074.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	504.00
5	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	257.00
6	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR	New	574.00	574.00
7	TO REMOVE AND INSTALL WIRE HARNESS ,CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT	New	531.00	504.00
8	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (S\$)			14,183.00	13,256.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >