

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012181/UQP3Q2**Date:** 15/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00186582202		
Claimant Vehicle No :	FBF967E	Insured Vehicle No :	SMF5228S		
Date of Loss:	27/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208585/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FBF967E</b>	Engine No:	G3J8E0094465
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Chassis No:	MH3SG4640KJ051411
Reg. Date:	15/01/2020 (Man. Year: 2019)	Odometer:	39547 km
Colour:	Black		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	110-80-14	Rear Tyre Size:	140-70-14
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,770.00	2,877.30	2,892.70	50.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	300.00	200.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,270.00</b>	<b>3,177.30</b>	<b>3,092.70</b>	<b>49.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	6,270.00	2,500.00	3,770.00	60.13
<b>+ GST 7.00/7.00% (S\$)</b>	438.90	175.00	263.90	60.13
<b>Nett Amount (S\$)</b>	<b>6,708.90</b>	<b>2,675.00</b>	<b>4,033.90</b>	<b>60.13</b>

**INSPECTION**

Date of Assignment:	09/12/2022		
Date Inspected:	08/12/2022	Inspected At:	Erzat Lee Motor Trading Pte Ltd (HQ) Synergy@KB 25, Kaki Bukit Road 4 #03-37 Singapore 417800
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Feb 2023)	
<b>Parts:</b>	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBF967E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FORK	Repair	550.00 F	*- FL
2	1		*FORK -UNDER BRACKET	Not Necessary	250.00 F	*- FL
3	1		*STEERING CONE	Not Necessary	150.00 F	*- FL
4	1		*FRONT FENDER	Cut	280.00 F	*220.00 FL
5	1		*FRONT TYRES SHAFT	Cut	180.00 F	*110.00 FL
6	1		*HEAD LAMP	Cracked	800.00 F	*699.00 FL
7	1		*HEAD LAMP STAY	Bent	250.00 F	*180.00 FL
8	1		*FRONT SIGNAL LIGHT LEFT	Cracked	180.00 F	*165.00 FL
9	1		*HANDLE BAR	Bent	300.00 F	*175.00 FL
10	1		*BAR END MIRROR	Damaged	150.00 F	*80.00 FL
11	1		*BRAKE LEVER LEFT	Bent	120.00 F	*68.00 FL
12	1		*FRONT FAIRING INNER COVER LEFT	Cracked	150.00 F	*150.00 FL
13	1		*FRONT FOOTREST BOARD LEFT	Cut	280.00 F	*280.00 FL
14	1		*FRONT FOOTREST UNDER COVER LEFT	Cut	180.00 F	*180.00 FL
15	1		*FRONT FAIRING COVER LEFT	Cracked	200.00 F	*200.00 FL
16	1		*REAR FOOTREST LEFT	Cracked	150.00 F	*80.00 FL
17	1		*AIR BOX COVER	Cut	180.00 F	*180.00 FL
18	1		*CVT COVER	Cut	250.00 F	*250.00 FL
19	1		*REAR FAIRING COVER LEFT	Cut	180.00 F	*180.00 FL
20	1		*REAR NUMBER PLATE	Not Necessary	30.00 F	*- FL
21	1		*FRONT FAIRING COVER RIGHT (CRACKED)	Not Consistent With The Impact	200.00 F	*- FL
22	1		*FRONT FAIRING INNER COVER RIGHT (CRACKED)	Not Consistent With The Impact	150.00 F	*- FL
23	1		*FRONT FOOTREST BOARD RIGHT (CUT)	Not Consistent With The Impact	280.00 F	*- FL
24	1		*FRONT FOOTREST UNDER COVER RIGHT (CUT)	Not Consistent With The Impact	180.00 F	*- FL
25	1		*EXHAUST COVER	Repair	150.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,770.00</b>	<b>3,197.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>319.70</b>
<b>Total Parts (\$\$)</b>	<b>5,770.00</b>	<b>2,877.30</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	500.00	300.00
<b>Gross Labour Cost (\$\$)</b>			<b>500.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >