

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012183/RWP3Q2  
**Date:** 18/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00228412202		
<b>Claimant Vehicle No :</b>	SLX803G	<b>Insured Vehicle No :</b>	SJL9618C		
Date of Loss:	30/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208754/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLX803G</b>	Engine No:	F4644081B48B20A
Make & Model:	BMW 318I, 2.0 (A)	Chassis No:	WBA70DY0X08C45657
Reg. Date:	16/03/2022 (Man. Year: 2021)	Odometer:	17589 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,203.10	2,133.05	70.05	3.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,172.00	495.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,870.10</b>	<b>4,305.05</b>	<b>565.05</b>	<b>11.60</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>389.61</b>	<b>344.40</b>	<b>45.21</b>	<b>11.60</b>
<b>Nett Amount (S\$)</b>	<b>5,259.71</b>	<b>4,649.45</b>	<b>610.26</b>	<b>11.60</b>

**INSPECTION**

Date of Assignment:	06/12/2022	
Date Inspected:	27/12/2022 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
<b>Parts:</b> 143	BMW 318I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLX803G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET OF MOUNT	Not Necessary	70.05 FS	*- FS
2	1		*REAR BUMPER TRIM PANEL BOTTOM (MSP)	Scratched	232.75 FS	*232.75 FS
3	1		*REAR BUMPER TRIM PANEL (MSP/MPA PDC)	Deformed	1,600.45 FS	*1,600.45 FS
4	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
5	1		*REAR BUMPER MOUNTING (MSP)	Cracked	147.50 FS	*147.50 FS
6	1		*REAR DIFFUSER	Cracked	72.35 FS	*72.35 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>2,203.10</b>	<b>2,133.05</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	TO PAINTING REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,667.00</b>
				<b>2,172.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >