

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22012188/RVY3E2**Date:** 22/12/2022**REFERENCE**

Insured/Claimant:	TEO CHIN LIAN	Policy No:	DMPG22011610	
Date of Loss:	01/12/2022	Nature of Claim:	OD	Claim No: CDMPG22002603

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF8779K		
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Engine No:	3ZRB746739
Reg. Date:	14/09/2016 (Man. Year: 2016)	Chassis No:	ZSU600074282
Colour:	Black	Odometer:	67891 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,404.30	6,317.10	1,087.20	14.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,710.00	370.00	17.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,484.30	8,027.10	1,457.20	15.36
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	9,484.30	7,527.10	1,957.20	20.64
+ GST 7.00/7.00% (S\$)	663.90	526.90	137.00	20.64
Nett Amount (S\$)	10,148.20	8,054.00	2,094.20	20.64

INSPECTION

Date of Assignment:	05/12/2022	
Date Inspected:	06/12/2022	Inspected At: Mova Automotive Pte Ltd 15 Fan Yong Road Singapore 629792
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8779K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET MOULDING (WCP)	Cracked	185.00 F	*185.00 F
2	1		*FRONT BONNET LOCK STAY PANEL (WCP)	Bent	138.00 F	*138.00 F
3	1		*FRONT GRILLE (WCP)	Cracked	320.00 F	*320.00 F
4	1		*FRONT GRILLE CLIPS (WCP)	Necessary	30.00 FS	*30.00 FS
5	1		*FRONT BUMPER (WCP)	Deformed	380.00 F	*380.00 F
6	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	155.00 F	*155.00 F
7	1		*FRONT BUMPER CLIPS (WCP)	Necessary	40.00 FS	*40.00 FS
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	300.00 F	*300.00 F
9	1		*FRONT BUMPER INNER SPONGE UPPER LH/RH (WCP)	O/S Cracked	144.00 F	*72.00 F
10	1		*FRONT BUMPER INNER SPONGE LOWER (WCP)	Deformed	88.00 F	*88.00 F
11	1		*FRONT BUMPER TOWING COVER RH (WCP)	Cracked	30.00 F	*30.00 F
12	1		*FRONT BUMPER SIDE RETAINER BRACKET LH (WCP)	Necessary	75.00 F	*75.00 F
13	1		*FRONT BUMPER SIDE RETAINER BRACKET RH (WCP)	Necessary	75.00 F	*75.00 F
14	1		*FRONT BUMPER LOWER LIP (WCP)	Deformed	210.00 F	*210.00 F
15	1		*FRONT SUPPORT PANEL TOP COVER CLIPS (WCP)	Not Necessary	40.00 FS	*- FS
16	1		*FRONT AIR COND CONDENSOR (WCP)	Not Necessary	880.00 F	*- F
17	1		*FRONT HEADLAMP LH (WCP)	Cracked	1,480.00 F	*1,480.00 F
18	1		*FRONT HEADLAMP RH (WCP)	Cracked	1,480.00 F	*1,480.00 F
19	1		*FRONT UNDER COVER (WCP)	Cracked	93.00 F	*93.00 F
20	1		*FRONT FENDER LH (WCP)	Bent	480.00 F	*480.00 F
21	2		*FRONT FENDER INNER LINER CLIPS LH/RH (WCP)	Necessary	80.00 FS	*80.00 FS
22	1		*FRONT NUMBER PLATE (WCP)	Cracked	30.00 FS	*30.00 FS
23	1		*FRONT NUMBER PLATE HOLDER (WCP)	Cracked	20.00 FS	*20.00 FS
24	1		*FRONT BONNET (REPAIR) (NPA)	Repair	-	*- F
25	1		*FRONT SUPPORT PANEL (REPAIR) (NPA)	Repair	-	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT RH FENDER (REPAIR) (NPA)	Repair	-	*- F
27	1		*FRONT LH DOOR (REPAIR) (NPA)	Repair	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,753.00	5,761.00
+ Margin on L,N Items 10.00/10.00% (S\$)	651.30	556.10
Total Parts (S\$)	7,404.30	6,317.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT & REPLACE FORNT AIR COND CONDENSOR, AIR COND PIPE & ETC.	New	100.00	0.00
2	TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH/RH, FRONT DOOR LH & ETC. BACK TO ORIGINAL CONDITIONS	New	600.00	500.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH, FRONT DOOR LH & ETC.	New	1,200.00	1,100.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	30.00
5	TO REFILL AIR COND GAS & VACUUM	New	100.00	80.00
Gross Labour Cost (S\$)			2,080.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >