



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22011610	Date of Loss:	01/12/2022
Vehicle Reg. No.:	SLF8779K	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TEO CHIN LIAN		
Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	14/09/2016
Vehicle Colour:	BLACK	Chassis No:	ZSU600074282
Engine No:	3ZRB746739		
Odometer:	67891 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	7,404.30
Miscellaneous Items	0.00
Labour	2,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,484.30
+ GST 7.00% (S\$)	663.90
Nett Amount (S\$)	10,148.20

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Finalize:

Parts: \$ 6117.10

S/Nett: \$ 200.00

Labour: \$ 1710.00

\$ 8027.10

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF8779K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET MOULDING <i>cm</i>	0.00	0.00	*185.00 F
2	1		*FRONT BONNET LOCK STAY PANEL <i>bt</i>	0.00	0.00	*138.00 F
3	1		*FRONT GRILLE <i>cm</i>	0.00	0.00	*320.00 F
4	1		*FRONT GRILLE CLIPS <i>nu</i>	0	0.00	*30.00 FS
5	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*380.00 F
6	1		*FRONT BUMPER LOWER GRILLE <i>cm</i>	0.00	0.00	*155.00 F
7	1		*FRONT BUMPER CLIPS <i>nu</i>	0	0.00	*40.00 FS
8	1		*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*300.00 F
9	2		*FRONT BUMPER INNER SPONGE UPPER LH/RH <i>de</i>	0.00	0.00	*144.00 F
10	1		*FRONT BUMPER INNER SPONGE LOWER <i>de</i>	0.00	0.00	*88.00 F
11	1		*FRONT BUMPER TOWING COVER RH <i>cm</i>	0.00	0.00	*30.00 F
12	1		*FRONT BUMPER SIDE RETAINER BRACKET LH <i>nu</i>	0.00	0.00	*75.00 F
13	1		*FRONT BUMPER SIDE RETAINER BRACKET RH <i>nu</i>	0.00	0.00	*75.00 F
14	1		*FRONT BUMPER LOWER LIP <i>de</i>	0.00	0.00	*210.00 F
15	1		*FRONT SUPPORT PANEL TOP COVER CLIPS <i>nu</i>	0	0.00	*40.00 FS
16	1		*FRONT AIR COND CONDENSOR <i>cm</i>	0.00	0.00	*880.00 F
17	1		*FRONT HEADLAMP LH <i>cm</i>	0.00	0.00	*1,480.00 F
18	1		*FRONT HEADLAMP RH <i>cm</i>	0.00	0.00	*1,480.00 F
19	1		*FRONT UNDER COVER <i>cm</i>	0.00	0.00	*93.00 F
20	1		*FRONT FENDER LH <i>bt</i>	0.00	0.00	*480.00 F
21	2		*FRONT FENDER INNER LINER CLIPS LH/RH <i>nu</i>	0	0.00	*80.00 FS
22	1		*FRONT NUMBER PLATE <i>cm</i>	0	0.00	*30.00 FS
23	1		*FRONT NUMBER PLATE HOLDER <i>cm</i>	0	0.00	*20.00 FS
24	1		*FRONT BONNET (REPAIR)	0.00	0.00	-
25	1		*FRONT SUPPORT PANEL (REPAIR)	0.00	0.00	-
26	1		*FRONT RH FENDER (REPAIR)	0.00	0.00	-
27	1		*FRONT LH DOOR (REPAIR)	0.00	0.00	-

F=Franchise part, S=SpcNett.

Sub Total (S\$)	5561.00	6,753.00
+ Margin on L,N Items 10.00% (S\$)	556.10	651.30
Total Parts (S\$)	6117.10	7,404.30

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

S/Nett: \$200.00

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, REFIT & REPLACE FRONT AIR COND CONDENSOR, AIR COND PIPE & ETC.	New	100.00 X
2	TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH/RH, FRONT DOOR LH & ETC. BACK TO ORIGINAL CONDITIONS	New	500 600.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH, FRONT DOOR LH & ETC.	New	1100 1200.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	30 80.00
5	TO REFILL AIR COND GAS & VACUUM	New	80 100.00
Gross Labour Cost (S\$)			1710.00 2,080.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul

Hp 900/10068

6 days

P/P

06/12/22 @ 1640

EXCESS: 500

Rever

Rasul ~~at~~ before paint

email: rasul@ikkauto.com