

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SDZ2662S

Not Authorised
Primary Repairing
4 days

No.	Qty	List Items		
1	1	Front bumper	Bu \$	15.98.20 ✓
2	1	Front bumper LH side parking sensor	\$	sun 254.50 ✓
3	1	Front bumper LH fog lamp cover	\$	ln 100.90 ✓
4	1	Front bumper LH fog lamp cover parking sensor	\$	sun 254.50 ✓
5	1	Front bumper LH fog lamp cover top garnish	\$	ln 90.90 ✓
6	1	Front bumper LH side retainer	\$	bit 30.20 ✓
7	1	Front bumper inner foam	\$	ln 78.90 X
8	1	Front bumper inner oil cooler	\$	827.20 ?
9	1	LH headlamp LED	\$	cm 2,800.00 ✓
10	1	Front LH fender	\$	n 693.70 X
11	1	Front LH fender under shield	\$	ln 135.99 X
12	1 set	Front fender under shield clips	\$	nn 40.00 X
13	1	Front LH sport rim	\$	nd 1,177.35 ✓
14	1	Front LH shock absorber	\$	397.60 ?
15	1	Front LH lower arm	\$	290.45 ?
16	1	Front LH knuckle arm	\$	593.90 ?
17	1	Front LH wheel hub & bearing	\$	519.00 ?
			\$	9,483.29
		Less 5%	\$	474.16
		Total :	\$	9,009.13

	Labour		
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	600.00 400
2	To putty and spray Spray Paintings charges.	\$	800.00 440
3	To check wirings and lightings.	\$	40.00 20
4	To remove, refit and reset front bumper parking sensor.	\$	80.00 60
5	To remove, refit front LH under carriages damage parts.	\$	250.00 ?
6	To conduct computerise wheel alignment test.	\$	80.00 60
7	To supply and apply anti rust treatment.	\$	nn 60.00 X
	Total :	\$	1,910.00

Total Parts and Labour : \$ 10,919.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date.

TO TUFF KOTE & UNDERCOAT
TO CHECK WIRING & ELECTRICAL SYSTEM.