

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012194/UQY3E2**Date:** 20/12/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002362613

Claimant Vehicle No : SLM6997Z**Insured Vehicle No :** FBP9361R

Date of Loss: 25/11/2022

Nature of Claim: TP Claim No: 293309

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLM6997Z**

Make & Model: HONDA VEZEL HYBRID, 1.5 RS (A)

Engine No: LEB5915680

Reg. Date: 07/04/2017 (Man. Year: 2016)

Chassis No: RU31215669

Colour: Blue

Odometer: 251106 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R18

Rear Tyre Size: 255/50 R18

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,428.00	1,911.36	2,516.64	56.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,120.00	1,190.00	51.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,738.00	3,031.36	3,706.64	55.01
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	6,738.00	2,400.00	4,338.00	64.38

INSPECTION

Date of Assignment: 06/12/2022

Date Inspected: 06/12/2022 Inspected At:

2ND Auto Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre
Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2022)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM6997Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,542.00 FL	*762.00 FL
2	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	248.00 FL	*56.00 FL
3	1		*LHS REAR BUMPER REFLECTOR	Not Necessary	128.00 FL	*- FL
4	1		*LHS REAR FENDER (NPA)	Repair	0.00 FL	*- FL
5	1		*LHS REAR FENDER WHEEL ARCH GARNISH	Torn	298.00 FL	*180.20 FL
6	1		*LHS REAR FENDER INNER SPLASH SHIELD (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*LHS REAR MUD FLAP	Not Necessary	92.00 FL	*- FL
8	1		*LHS REAR BUMPER SIDE	Torn	542.50 FL	*235.40 FL
9	1		*REAR TAILGATE (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*LHS TAILLAMP	Broken	982.00 FL	*480.60 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
12	1		*SET LHS REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
13	1		*LHS REAR SPORTS RIM	Cut	980.00 FS	*500.00 FS
14	1		*REVERSE SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*REAR TAILGATE H BADGE	Not Necessary	36.00 FS	*- FS
16	1		*REAR TAILGATE RS EMBLEM	Not Necessary	48.00 FS	*- FS
17	1		*REAR TAILGATE HYBRID EMBLEM PLATE	Not Necessary	98.00 FS	*- FS
18	1		*SET LHS REAR FENDER WHEEL ARCH GARNISH CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,194.50	2,254.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	766.50	342.84
Total Parts (\$\$)	4,428.00	1,911.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; AND REPLACE DAMAGED PARTS & COMPONENTS	New	1,000.00	400.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED (REAR TAILGATE)	New	1,000.00	600.00
3	TO CHECK WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	90.00	20.00
4	TO REMOVE AND REFIX REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	100.00	40.00
5	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	60.00
Gross Labour Cost (S\$)			2,310.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >