

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012195/KWY3E2**Date:** 29/12/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000881351

Claimant Vehicle No : SMA9144A**Insured Vehicle No :** SMF3017Y

Date of Loss: 03/12/2022

Nature of Claim: TP

Claim No: 293247

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMA9144A**

Make & Model: TOYOTA VOXY HYBRID, 1.8 V CVT (A)

Engine No: 2ZR0B11325

Reg. Date: 22/06/2018 (Man. Year: 2018)

Chassis No: ZWR800307046

Colour: Metallic Grey

Odometer: 177049 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,678.99	4,080.82	598.17	12.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	2,080.00	1,200.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,958.99	6,160.82	1,798.17	22.59
+ GST 7.00/7.00% (S\$)	557.13	431.26	125.87	22.59
Nett Amount (S\$)	8,516.12	6,592.08	1,924.04	22.59

INSPECTION

Date of Assignment: 06/12/2022

Date Inspected: 13/12/2022 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-15, Sin Ming AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$6,160.83

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 V CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA9144A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,420.00 FL	*1,420.00 FL
2	1		*FRONT LH DOOR WEATHERSTRIP	Serviceable	185.00 FL	*- FL
3	1		*FRONT LH DOOR TAPE	Necessary	120.00 FL	*120.00 FL
4	1		*REAR LH DOOR	Bent	1,540.00 FL	*1,540.00 FL
5	1		*REAR LH DOOR WEATHERSTRIP	Serviceable	185.00 FL	*- FL
6	1		*REAR LH DOOR TAPE	Necessary	120.00 FL	*120.00 FL
7	15		*DOOR RIVETS	Not Necessary	75.00 FL	*- FL
8	1		*LH ROCKER PANEL GARNISH	Buckled	954.60 FL	*781.10 FL
9	8		*ROCKER GARNISH CLIPS	Necessary	48.00 FL	*48.00 FL
10	1		*REAR DOOR TAPE LH	Necessary	75.00 FL	*75.00 FL
11	1		*REAR DOOR WEATHERSTRIP LH - SENSOR	Cut	1,384.65 FL	*1,205.60 FL
12	1		*FRONT DOOR TAPE LH NO.1	Necessary	55.30 FL	*55.30 FL
13	1		*FRONT DOOR TAPE UPPER LH	Necessary	76.10 FL	*76.10 FL
					Sub Total (\$\$)	6,238.65
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,559.66
					Total Parts (\$\$)	4,678.99

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	600.00
2	TO APPLY ANTI RUST COATING	New	150.00	60.00
3	TO REMOVE AND TRANSFER DOOR FITTINGS TO NEW DOOR	New	350.00	120.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
5	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	1,280.00
Gross Labour Cost (\$\$)			3,280.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >