

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22012197/KWY3M4**Date:** 11/01/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP320829
<b>Claimant Vehicle No :</b>	GBM734Z	<b>Insured Vehicle No :</b>	SMV4423S
Date of Loss:	24/11/2022	Nature of Claim:	TP
		Claim No:	MPC03864/GN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBM734Z</b>	Engine No:	R06A3162119
Make & Model:	NISSAN NV100, 658cc DX GL PKG (A)	Chassis No:	DR17V613681
Reg. Date:	28/10/2022 (Man. Year: 2022)	Odometer:	3909 km
Colour:	White		
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	145/80R12	Rear Tyre Size:	145/80R12
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,887.78	1,332.95	1,554.83	53.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,100.00	960.00	46.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,947.78</b>	<b>2,432.95</b>	<b>2,514.83</b>	<b>50.83</b>
<b>+ GST 8.00/8.00% (S\$)</b>	395.82	194.64	201.18	50.83
<b>Nett Amount (S\$)</b>	<b>5,343.60</b>	<b>2,627.59</b>	<b>2,716.01</b>	<b>50.83</b>

INSPECTION

Date of Assignment:	06/12/2022	160 SIN MING DRIVE #01-13, SIN MING AUTO CITY
Date Inspected:	03/01/2023 Inspected At:	SINGAPORE 575722
		REPAIRER: BIFROST AUTO PTE LTD
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$2,432.96

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Jan 2023)	
Parts:	N/A	NISSAN NV100 658cc DX GL PKG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBM734Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	560.85 FL	*560.85 FL
2	10		*REAR BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
3	1		*REAR END PANEL	Repair	256.05 FL	*- FL
4	1		*TAILGATE	Repair	961.85 FL	*- FL
5	1		*TAILGATE EMBLEM	Necessary	85.60 FL	*85.60 FL
6	1		*NV100 STICKER	Necessary	68.50 FL	*68.50 FL
7	1		*REAR WINDSCREEN MOULDING	Not Necessary	120.80 FL	*- FL
8	1		*REAR BUMPER SENSOR	Dented	400.00 FS	*320.00 FS
9	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
10	1		*5 PAX STICKER	Necessary	15.00 FS	*15.00 FS
11	1		*REAR NUMPER PLATE	Dented	40.00 FS	*40.00 FS
12	1		*REAR WINDSCREEN STICKER	Not Necessary	40.00 FS	*- FS
13	1		*COMPANYS LOGO STICKER	Necessary	480.00 FS	*250.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					3,098.65	1,409.95
- List Item Discount on L Items 10.00/10.00% (\$\$)					210.87	77.00
Total Parts (\$\$)					2,887.78	1,332.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	ANTI-RUST	New	80.00	0.00
4	TRANSFER TAIL GATE	New	80.00	0.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,060.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >