

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 9698 8882 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: LIBERTY

Att: Motor Claims Dept

ACCIDENT INVOLVING SKE86X [YOUR INSURED] & SLF2491D [OUR CLIENT]
ON 02/12/2022.

ESTIMATED REPAIR COSTS FOR SLF2491D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	ROCKER PANEL GARNISH RH <i>HH</i>	\$ 1,582.30	X
1PC	REAR WHEEL BEARING RH <i>HH</i>	\$ 398.00	X
1PC	REAR WHEEL BEARING HUB RH <i>HH</i>	\$ 452.00	X
1PC	REAR ABSORBER RH <i>HH</i>	\$ 974.50	X
1PC	REAR LOWER ARM RH <i>HH</i>	\$ 985.00	X
1PC	REAR KNUCKLE ARM RH <i>HH</i>	\$ 1,294.00	X
1PC	REAR THRUST ARM RH <i>HH</i>	\$ 852.00	X
1PC	REAR CONTROL ARM RH <i>HH</i>	\$ 782.00	X
1PC	REAR UPPER ARM RH <i>HH</i>	\$ 894.00	X
1PC	REAR STABILIZER LINK RH <i>HH</i>	\$ 398.00	X
1PC	REAR FENDER RH <i>key</i>	\$ 3,985.00	X
1PC	REAR FENDER INNER SHIELD RH <i>HH</i>	\$ 414.00	X
1PC	REAR BUMPER <i>key</i>	\$ 2,752.00	X
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$398.51 EACH <i>HH</i>	\$ 797.02	X
1PC	REAR WINDSCREEN MOULDING <i>HH</i>	\$ 395.00	X
1PC	REAR DOOR RH <i>HH</i>	\$ 2,689.00	X
1PC	REAR DOOR WINDOW MOULDING RH <i>HH</i>	\$ 185.00	X
1PC	REAR DOOR LOCK RH <i>HH</i>	\$ 452.00	X
1PC	REAR DOOR WEATHER STRIP RH <i>HH</i>	\$ 395.00	X
1PC	REAR DOOR INNER TRIM BOARD RH <i>HH</i>	\$ 1,674.00	X
2PCS	REAR DOOR HINGE RH @ \$210.00 EACH <i>HH</i>	\$ 420.00	X
1PC	REAR DOOR BLACK PLASTIC RH <i>HH</i>	\$ 184.00	X
1PC	ROCKER PANEL GARNISH RH <i>HH</i>	\$ 1,582.30	X

PARTS SUM: \$ 24,536.12

PARTS LESS 10%: \$ 2,453.61

PARTS TOTAL: \$ 22,082.51

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1 PC SPORT RIM HH	\$ 2,000.00 X
*	TO SUPPLY 1 PC TYRE HH	\$ 800.00 X
*	TO SUPPLY REAR BUMPER CLIPS HH	\$ 80.00 X
*	TO SUPPLY REAR FENDER SEALANT HH	\$ 80.00 X
*	TO SUPPLY REAR WINDSCREEN SEALANT HH	\$ 80.00 X
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS HH	\$ 80.00 X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00 200/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00 300/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 HH
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 HH
*	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 HH
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00 HH
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00 HH
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$ 100.00 HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 HH
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 HH
*	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	\$ 120.00 HH

LABOUR & S/N TOTAL: \$ 9,360.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 31,442.51

14/12/2022 e 1700m P/P 500.00
 HA Auker
 P/P
 2 dgs.
 Jm
 Jkk dtd
 P/P after 14/12/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: