

ASS. REC BY: Toupin

REF: CS/INC27012202/Tuy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YQ 6693A

Policy No. _____

Claims No. MT/1198795-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 970K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Steel

Veh No: GBK 2010B Yr Regn: 2029 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 80530 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STFHT02 P900250025

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/R15

R: 24

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Greenlander

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/11/2022 D.O.I. 7/12/22

Survey held at Efficient Auto

Des. of Damages: Frt / Rear / O/S / NI / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/4/23 Lump Sum \$8100 confirmed by email (Red 8637.63, 51%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 10/4/23-typist

Rep. Format: TP

Lump Sum / ~~1198795~~ / \$8100

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Office

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

635R

Vehicle Details

Vehicle No.:

GBK2010B

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Nov 2022

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE VAN TURBO 5DR MT

Primary Colour:

Silver

Manufacturing Year:

2019

Engine No.:

1KDB019714

Chassis No.:

JTFHT02P900250025

Maximum Power Output:

-

Open Market Value:

\$28,138.00

Original Registration Date:

31 Jan 2020

First Registration Date:

31 Jan 2020

Transfer Count:

0

Actual ARF Paid:

\$1,407.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

30 Jan 2030

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$25,001.00

COE Rebate Amount:

\$17,930.00

Total Rebate Amount:

\$17,930.00

The information contained herein is correct as at 28 Nov 2022

OK

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

VEHICLE NO : GBK2010B

MAKE & MODEL : TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P900250025

DATE : 01 DEC 2022

CLAIM TYPE : TP CLAIM

D.O.A : 27 NOV 2022

TO : NTUC

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	FRONT BUMPER		\$ 586.80	\$ ann 586.80 ✓
2	1	FRONT BUMPER RETAINER LH		\$ 154.20	\$ de 154.20 ✓
3	1	WIRING HARNESS HOLDER LH		\$ 127.60	\$ x nn 127.60
4	1	HEADLAMP ASSY LH		\$ 807.80	\$ ann 807.80 ✓
5	1	HEADLAMP BRACKET LH		\$ 22.30	\$ x nn 22.30
6	1	CORNER PANEL LH		\$ 290.50	\$ bt 290.50 ✓
7	1	SIDE MIRROR ASSY LH		\$ 1250 1,298.00	\$ bro 1,298.00 1050
8	1	FRONT STEP GARNISH LH		\$ 175.40	\$ x nn 175.40
9	1	LH FRONT DOOR		\$ 1678 2,038.90	\$ bt 2,038.90 1438
10	1	LH FRONT DOOR WINDOW GLASS		\$ 636.60	\$ x nn 636.60
11	1	LH FRONT DOOR OUTER MLDG		\$ 107.20	\$ de 107.20 ✓
12	1	LH FRONT DOOR OUTER HANDLE		\$ 203.50	\$ cut 203.50 ✓
13	1	LH CENTRE PILLAR		\$ 787.70	\$ bt 787.70 711
14	1	LH SLIDE DOOR		\$ 1745 2,069.20	\$ bt 2,069.20 1545
15	1	LH SLIDE DOOR WEATHERSTRIP		\$ 417.20	\$ x nn 417.20
16	1	LH SLIDE DOOR LOCK REAR		\$ 277.70	\$ x nn 277.70
17	1	LH SLIDE DOOR LOCK FRONT		\$ 624.70	\$ x nn 624.70
18	1	LH SLIDE DOOR HINGE CENTER		\$ 182.30	\$ x nn 182.30
19	1	LH SLIDE DOOR ROLLER LOWER		\$ 361.40	\$ x nn 361.40
20	1	LH SLIDE DOOR INNER STEP PANEL		\$ 1,329.70	\$ x nn 1,329.70
21	1	LH SLIDE DOOR RAIL GUIDE		\$ 558.60	\$ Ry 558.60
22	1	LH REAR FENDER		\$ 1,675.80	\$ bt 1,675.80 ✓
23	1	FUEL LID COVER		\$ 147.70	\$ cut 147.70 ✓
24	1	LH TAIL LAMP		\$ 331.10	\$ cut 331.10 ✓
25	1	REAR BUMPER		\$ 491.60	\$ Ry 491.60
				\$ 15,703.50	\$ 15,703.50

9048.60
-25%
6786.45

TOTAL PRICE \$ 15,703.50
LESS 25% \$ 3,925.88
SUB TOTAL PRICE \$ 11,777.63

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	LH SLIDE DOOR TRIMBOARD CLIP SET		\$ 50.00	\$ x nn 50.00
2	1	LH FRT DOOR CO.REG STICKER		\$ 30.00	\$ cut 30.00
3	2	WHEEL RIM		\$ 250.00	\$ Ry 500.00
4	2	TYRES		\$ 150.00	\$ x nn 300.00
5	1	SEALANT		\$ 80.00	\$ 40.00 80.00

TOTAL S/NETT

\$ 560.00 \$ 960.00

Labour Charges

70

1	To cut & weld -damaged panels LH side portion / To panel beat & align door, remove & replace damaged parts.	\$ 1,800.00	1300
2	To apply anti rust coat and Tuff Kote repaired areas	\$ 150.00	50
3	To check and rectify lighting & wiring.	\$ 100.00	30
4	To Spray painting for LH Portions, & affected areas.	\$ 1,500.00	1400
5	To transfer front door & slide door components to new door.	\$ 300.00	60
6	To do tyre balancing & wheel alignment	\$ 150.00	30

TOTAL LABOUR

2870

\$ 4,000.00

Total Cost of Repairs

\$ 16,737.63

(Total parts + Total S/Nett + Total Labour Cost)

9726.45

L/S - 7781.16
= 7800

Taufik 97495749
'wp' 7/17/22 @ 345 pm
c/s Resurvey after repair
Taufik @ 11hants.wm
8-9 days

UKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

16:13 M

   84% 



JAE AH HAO Toyota

online



JAE AH HAO Toyota

OK I change

bro when will exchange? 10:14 ✓✓

haven't come 10:14 ✓✓

eh..... 10:14

i check 10:14

GBK2010B T. HIACE
JTFHT02P900250025

SIDE MIRROR ASSY LH
FRT DOOR LH
SLIDING DOOR LH

16:11 ✓✓

bro list price please? 16:11 ✓✓

thanks 16:11 ✓✓

GBK2010B T. HIACE
JTFHT02P900250025

SIDE MIRROR ASSY LH \$1441.30
FRT DOOR LH \$2263.90
SLIDING DOOR LH \$2297.60

16:12

Thanks bro 🙏 16:13 ✓✓

 Message

