



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5202J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	1,175.00	1,175.00
10	REAR BUMPER CLIPS @\$4.00	NECESSARY	40.00	40.00
2	REAR BUMPER TOW COVER @\$55.00	MISSING (1PC ONLY)	110.00	55.00
4	REAR BUMPER RIVET @\$5.00	NECESSARY	20.00	20.00
1	REAR REINFORCEMENT	NOT NECESSARY	545.00	-
	LESS 20% DISCOUNT		-378.00	-258.00
			1,512.00	1,032.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			280.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACED REAR REVERSE SENSOR.		120.00	40.00
	TO KNOCKING & PANEL BEATING.		600.00	200.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		500.00	200.00
			1,220.00	440.00
<b>GRAND TOTAL</b>			<b>3,012.00</b>	<b>1,472.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,150.00</b>

Report Ref No. CS/SPF22012205/Rqy3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,150-\$1,200**

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.