

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012211/UYA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800021846
Claimant Vehicle No :	GBC8283H	Insured Vehicle No :	SLW8602Y
Date of Loss:	05/12/2022	Nature of Claim:	TP
		Claim No:	7945905293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC8283H		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)	Engine No:	4P10A92823
Reg. Date:	20/12/2013 (Man. Year: 2013)	Chassis No:	FEA01BA00039
Colour:	White	Odometer:	352218 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,834.50	13,673.16	17,161.34	55.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	3,100.00	1,550.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,484.50	16,773.16	18,711.34	52.73
Approved Total (Overridden) (S\$)		13,000.00		
Nett Amount (S\$)	35,484.50	13,000.00	22,484.50	63.36
+ Loss of Use (10.0 x S\$80.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		214.00		
Nett Liability (S\$)		14,016.00		

INSPECTION

Date of Assignment:	07/12/2022	
Date Inspected:	07/12/2022 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	2,436.60 F	*1,660.58 FL
2	1		*FRONT GRILLE	Cracked	1,105.70 F	*785.21 FL
3	1		*SET FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
4	1		*FRONT MITSUBISHI LOGO MOTIF	Not Necessary	187.00 F	*- F
5	1		*FRONT CANTER EMBLEM	Not Necessary	75.40 F	*- FL
6	1		*FRONT AIRCON COOLING COIL UNIT	Cracked	3,591.70 F	*2,823.15 FL
7	1		*FRONT AIRCON CONDENSER	Punctured	1,439.60 F	*1,120.00 FL
8	1		*FRONT AIRCON CONDENSER FAN ASSY	Not Necessary	1,146.20 F	*- FL
9	1		*FRONT WIPER PANEL	Repair	1,482.10 F	*- FL
10	1		*FRONT WINDSCREEN RUBBER	Cut	492.30 F	*366.01 FL
11	1		*FRONT POWER STEERING RESERVOIR	Cracked	108.60 F	*108.60 FL
12	1		*FRONT FUSE BOX	Cracked	3,655.30 F	*2,150.00 FL
13	1		*FRONT BUMPER	Distorted	1,117.20 F	*780.90 FL
14	1		*FRONT LH BUMPER BRACKET	Bent	196.30 F	*196.30 FL
15	1		*FRONT LH BUMPER SIDE	Broken	441.70 F	*319.82 FL
16	1		*SET FRONT LH BUMPER SIDE CLIPS	Not Necessary	45.00 FS	*- FS
17	1		*FRONT LH CORNER PANEL	Distorted	486.90 F	*486.90 FL
18	1		*SET FRONT LH CORNER PANEL CLIPS	Not Necessary	28.00 FS	*- FS
19	1		*FRONT LH CORNER PANEL TOP COVER	Broken	114.00 F	*114.00 FL
20	1		*FRONT LH MIRROR ARM	Cracked	545.20 F	*472.39 FL
21	1		*FRONT LH MIRROR ARM COVER	Missing	89.30 F	*89.30 FL
22	1		*FRONT LH SIDE MIRROR ROUND	Broken	110.50 F	*110.50 FL
23	1		*FRONT LH SIDE MIRROR RECTANGLE	Broken	188.80 F	*188.80 FL
24	1		*FRONT LH HEAD LAMP	Broken	856.40 F	*665.10 FL
25	1		*FRONT LH HEAD LAMP BULB	Missing	48.00 FS	*5.00 FS
26	1		*SET FRONT LH HEADLAMP CLIPS	Not Necessary	30.00 FS	*- FS
27	1		*FRONT LH HEAD LAMP GRILLE (COVER)	No such part	581.00 F	*- FL
28	1		*FRONT LH HEADLAMP PANEL	No such part	1,149.90 F	*- FL
29	1		*FRONT LH SIGNAL LAMP	Broken	313.60 F	*208.02 FL
30	1		*FRONT LH SIGNAL LAMP BULB	Missing	18.00 FS	*5.00 FS
31	1		*SET FRONT LH SIGNAL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
32	1		*FRONT LH SIDE LAMP	Broken	259.20 F	*184.20 FL
33	1		*FRONT LH STEP PANEL	Bent	338.10 F	*338.10 FL
34	1		*FRONT LH STEP GARNISH LOWER	Broken	613.20 F	*288.50 FL
35	1		*FRONT LH STEP PANEL TOP GARNISH	Deformed	647.40 F	*292.00 FL
36	1		*FRONT LH DOOR	Distorted	1,910.50 F	*1,566.10 FL
37	1		*FRONT LH DOOR BOARD	Deformed	617.80 F	*565.00 FL
38	1		*FRONT LH DOOR OUTER GARISH	Distorted	195.40 F	*195.40 FL
39	1		*FRONT LH DOOR WEATHERSTRIP	Torn	266.50 F	*266.50 FL
40	1		*FRONT LH DOOR LOCK	Dented / Jammed	417.00 F	*365.00 FL
41	1		*FRONT LH DOOR HINGE TOP & LOWER	Lower Bent	289.00 F	*144.50 FL
42	1		*FRONT LH DOOR GLASS REGULATOR	Not Necessary	1,317.70 F	*- FL
43	1		*FRONT LH DOOR PILLAR	Badly Dented	1,482.40 F	*1,100.00 FL
44	1		*FRONT LH FREEZER BOX ALUMINIUM COVER	Dented	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,834.50	18,160.88
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	4,487.72
Total Parts (\$\$)	30,834.50	13,673.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST	New	120.00	80.00
2	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	300.00	100.00
3	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	300.00	20.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,800.00	1,400.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,600.00	1,200.00
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	180.00	100.00
7	REMOVE & REINSTALL DASHBOARD, METER INSTRUMENTS, DISCONNECT WIRING & ETCS...	New	350.00	200.00
Gross Labour Cost (\$\$)			4,650.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >