

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012212/UYA3Q2**Date:** 17/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070091948
Claimant Vehicle No :	GBF2310L	Insured Vehicle No :	GBG1947B
Date of Loss:	07/11/2022	Nature of Claim:	TP
		Claim No:	5425695056SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2310L	Engine No:	1KD2617156
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	KDY2318025035
Reg. Date:	02/08/2016 (Man. Year: 2016)	Odometer:	242139 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,823.00	1,754.12	2,068.88	54.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	830.00	250.00	23.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,903.00	2,584.12	2,318.88	47.30
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,903.00	2,000.00	2,903.00	59.21
+ GST 7.00/7.00% (S\$)	343.21	140.00	203.21	59.21
Nett Amount (S\$)	5,246.21	2,140.00	3,106.21	59.21
+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,655.60		

INSPECTION

Date of Assignment:	07/12/2022	
Date Inspected:	07/12/2022	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,317.50 F	*1,317.50 FL
2	1		*REAR TAILGATE 1500KG STICKER	Necessary	38.00 F	*38.00 FL
3	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
4	1		*REAR TAILGATE DYNA STICKER	Necessary	40.00 F	*40.00 FL
5	1		*REAR TAILGATE 13 PAX STICKER	Necessary	15.00 FS	*10.00 FS
6	1		*RIGHT SIDEGATE LOCK DEVICE	Bent	182.50 F	*182.50 FL
7	1		*REAR END DECK PANEL	Repair	1,218.00 F	*- FL
8	2		*REAR END DECK PANEL REFLECTOR	Cracked	185.60 F	*185.60 FL
9	1		*RIGHT TAIL LAMP	Cracked	281.90 F	*281.90 FL
10	1		*RIGHT TAIL LAMP PANEL	Repair	284.50 F	*- FL
11	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
12	1		*REAR LICENCE PLATE	Serviceable	45.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,823.00	2,265.50
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	511.38
Total Parts (\$)	3,823.00	1,754.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER REAR TAILGATE ALUMINIUM BOARD	New	80.00	0.00
2	CHECK WIRING	New	50.00	20.00
3	ANTI RUST PROOFING	New	50.00	30.00
4	PANEL BEATING	New	400.00	380.00
5	PAINTWORK	New	500.00	400.00
Gross Labour Cost (S\$)			1,080.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >