

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22012214/KPA3Q2**Date:** 13/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002128670-01
Claimant Vehicle No :	SJU3324S	Insured Vehicle No :	SGJ8101D
Date of Loss:	03/12/2022	Nature of Claim:	TP
		Claim No:	202222008613

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU3324S		
Make & Model:	NISSAN LATIO, 1.5 AT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	HR15102056B
Reg. Date:	30/11/2009 (Man. Year: 2009)	Chassis No:	JN1BAAC11Z0021427
Colour:	Metallic Black	Odometer:	343020 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,011.68	3,648.81	4,362.87	54.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,180.00	1,580.00	57.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,771.68	4,828.81	5,942.87	55.17
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	10,771.68	3,800.00	6,971.68	64.72
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,402.00		

INSPECTION

Date of Assignment:	06/12/2022	
Date Inspected:	05/12/2022 Inspected At:	TSR AUTOMOTIVE PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2023)
Parts:	143	NISSAN LATIO 1.5 AT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU3324S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	598.00 FL	*- FL
2	1		*FRONT BUMPER RETAINER LH	Serviceable	140.00 FL	*- FL
3	1		*HEADLAMP LH	Serviceable	720.00 FL	*- FL
4	1		*FRONT FENDER LH	Bent / Warped	485.00 FL	*485.00 FL
5	1		*FRONT FENDER UNDERSHIELD LH	Serviceable	161.20 FL	*- FL
6	1		*FRONT DOOR LH	Warped	1,120.00 FL	*1,120.00 FL
7	1		*FRONT DOOR HINGE LH	Repair	440.00 FL	*- FL
8	1		*FRONT DOOR CHECKER LH	Serviceable	185.00 FL	*- FL
9	1		*FRONT DOOR TRIM BOARD LH	Serviceable	620.00 FL	*- FL
10	1		*FRONT DOOR PILLAR STRUCTURE (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT WHEELHUB LH	No such part	340.00 FL	*- FL
12	1		*FRONT WHEELHUB BEARING LH	Necessary	313.20 FL	*293.70 FL
13	1		*FRONT SUSPENSION LH	Bent	567.80 FL	*347.60 FL
14	1		*FRONT KNUCKLE ARM LH	Bent	515.00 FL	*376.80 FL
15	1		*FRONT LOWER ARM LH	Distorted	552.00 FL	*397.80 FL
16	1		*FRONT STABILIZER BAR LH	Serviceable	198.00 FL	*- FL
17	1		*FRONT TIE ROD END LH	Serviceable	180.00 FL	*- FL
18	1		*ROCKER PANEL LH (NPA)	Repair	0.00 FL	*- FL
19	1		*FRONT RIM LH	Dented	600.00 FS	*280.00 FS
20	10		*FRONT BUMPER CLIPS	Not Necessary	45.00 FS	*- FS
21	10		*FRONT FENDER UNDERSHIELD CLIPS	Not Necessary	45.00 FS	*- FS
22	1		*ROCKER PANEL GARNISH LH	Buckled / Dented	900.00 FS	*650.00 FS
					Sub Total (S\$)	8,725.20 3,950.90
					- List Item Discount on L Items 10.00/10.00% (S\$)	713.52 302.09
					Total Parts (S\$)	8,011.68 3,648.81

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DO CUTTING ,WELDING ,REPLACE REMOVE REFIX ,REPAIR REAR ACCIDENT AFFECTED AREA	New	1,000.00	400.00
2	TO CHECK WIRING SYSTEM ETC	New	90.00	20.00
3	TO DO SEALANT ,WATERPROOFING SEAL GAP ETC	New	150.00	0.00
4	TO DO ANTI RUST FOR ACCIDENT AFFECTED AREA	New	90.00	60.00
5	TRANSFER DOOR PARTS TO ANOTHER DOOR	New	100.00	60.00
6	TO REPLACE FRONT UNDERCARRIAGE	New	250.00	180.00
7	TO DO COMPUTER WHEEL ALIGNMENT AFTER REPAIR	New	80.00	60.00
8	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA (INNER AND OUTER)	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,760.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >