COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Updated 11 Feb 2020

DATE:

MODEL:

05.12.22

Hyundai i40 (Front)

INSURANCE: ALLIANZ

	Hyundai i40 (Front)					
HICLE NO.: SH6289U			MVA: <u>JUMANI</u>			
ART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT		
	Radiator Grille H Emblem			\$39.50	/ms	
	Radiator Grille			\$1,480.00	CRF	
	Front Bumper Cover			\$1,052.20	/ CR	
	Front Bumper Sponge			\$379.20	2	
	Front Bumper Reinforcement			\$588.40	?	
- 1	Front Bumper Grille (LH/RH)		\$187.20	\$374.40	/ DE	
	Front Number Plate				Nett /	
- 1	Front No. Plate Trim Cover			\$30.00	Nett -	
	Front Bumper Bracket Top (LH/RH)		\$44.80	\$89.60	2	
- 1	Headlamp Support Panel Assy		• • • • • • • • • • • • • • • • • • • •	\$907.40	7	
- 1	Headlamp RH			\$1,388.00	1cr	
	leadlamp Halogen Bulb (LH/RH)		\$14.40	\$28.80	?	
	Radiator		• • • • • • • • • • • • • • • • • • • •	\$1,637.20	?	
				\$1,194.20	?	
- 1	adiator Fan Blade, Cowling, Motor Assy		\$13.00	\$26.00		
- 1	adiator Bracket (LH/RH)			\$70.00		
- 1	adiator Guard		\$35.00			
- 1	orn Unit (LH/RH)		\$73.80	\$147.60	1 -	
Ho	orn Wire			\$156.60		
Air	con Discharge Hose			\$194.40	1 -	
Air	con condenser			\$647.80		
Aire	con Receiver			\$71.50		
Airc	con suction hose			\$624.00	?	
Airc	con discharge hose			\$194.40	?	
- 1	Fender RH			\$663.00	10	
- 1	wheel cap			\$217.20	10	
	Fender sheild RH			\$174.90		
SUB	TOTAL			\$13,214.80		
	S 20%			\$3,303.70	1	
	COUNTED TOTAL			\$9,911.10	1	
				V.		
	ur Charge			120	7	
	Beating Change			1200 \$200-00		
	Painting Charge			\$ 890.00		
1	Charge			\$ 50.00		
Tuff Ko				\$ 50.00	-	
	Charge (King Dolly)			\$150.00	12	
1	e/Refix Radiator			\$120.00		
Remove	e/Refix Aircon & Refill Gas			\$120.00	?	
1				\$2,490.00		
		1			1	

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT			
TOTAL LA				\$ 2,490.00			
ESTIMATE	TOTAL			\$ 12,401.11			
This is a	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.						

COMFORTDELGRO ENGINEERING PTE LTD

Rear fender dust cover LH

REPAIR ESTIMATE*

VEHICLE NO SH6829U

MAKE HYUANDAI **DATE 05.12.22** INS ALLAINZ

MVA JUMANI MODEL : i40 (REAR) Amount **Unit Price** Type **Q**ty Parts Description/ Labour DD 2,609.80 **Boot Lid** /TN \$ 96.50 Boot Lid Rubber 1BT 824.60 142.30 \$ Boot Lid Hinge (LH/RH) ? 142.30 \$ **Boot Lid Lock Upper** \$ 31.70 Boot Lid Lock Lower MIS \$ 63.10 Boot Lid 'H' Emblem -M15 \$ 52.40 Boot Lid CRDI Plate Nett MIS \$ 30.00 **Boot Lid Comfort Logo** 40.00 | Nett / S \$ Boot Lid Comfort APPS Logo \$ Nett / MUS 30.00 Boot Lid comfort Tel.no sticker / GA 67.90 33.95 \$ \$ Licence Lamp (LH/RH) Nett MS \$ 50.00 Rear No.Plate \$ 65.65 Boot Lid Absorber \$ 343.90 **Boot Lid Trimboard** \$ 11.00 Boot Lid Trimboard Clips (10pcs) \$ 85.00 **Bootlid Moulding** NEC \$ 67.90 Bootlid i40 Emblem \$ 227.90 Bootlid Lower Garnish MIS \$ 553.00 Rear Bumper / DEF 428.40 Rear Bumper Reinforcement Buc 321.20 \$ 160.60 Rear Bumper Reinforcement Bracket (LH/RH) Nett /MIS \$ 135.70 Rear Bumper Reverse Sensor DEF \$ 119.50 Rear Bumper Sponge \$ MIS 228.00 Rear Bumper Under Cover CRA \$ 32.00 \$ 64.00 Rear Bumper Reflector Lamp (LH/RH) / CRA \$ 35.60 \$ 71.20 Rear Bumper Bracket (LH/RH) -NEC \$ 22.00 Rear Bumper Clips 10 pcs Nett /TW \$ Rear Bumper Rubber Mat 50.00 / CRA Tail Lamp (LH/RH) \$ 697.80 DD \$ Rear Panel 526.70 BUC \$ Rear Panel Garnish 57.70 100 Rear Fender (LH/RH) \$ 2,171.40 Rear Windscreen Sealant \$ 46.00 Nett /NE Rear windscreen Glass CRA \$ 607.20 XR Frt Door Assy RH \$ 2,707.70 \$ XR 2,416.80 \$ 4,833.60 LKK Auto Consultants hence notify
the Repairer of the following repairer of the following repairer. \$ 1,310.60 Rear Exhaustopipes (EM/RPP) oled versuses of . \$ 1,935.40 \$ 3,870.80 To dispiay gamaged part(s) during resumes.
 Parts prices are subject to confirmation. \$ 730.10 Third party survey is on a "tona frequency range Teal" \$ 852.50 Rear Fender Sheild Life Indianisation lage I ou xsvc \$ 169.30 Supplementary item is subject to final aparts. I must be resurveyed and 4,232.50 CRA Bootlid Lamp (LH/RH) \$ 622.20 \$ 1,244.40 Rear Cross member Signature: \$ 2,021.50 Date: Rear tray Luggs side LH \$

232.60

51.60

\$

Fuel Tank Lip Cover /MIS	S S	82.10 29.30
Fuel Tank cap / MIS		2,
SUB TOTAL	\$	33,308.05 8327
LESS 20% DISCOUNTED TOTAL		24981
Labour Charge	1200 \$	2 ,800.00
Panel Beating	1,750 \$ \$ 1,250 \$ \$ 60 \$ \$,
Spray Painting Charge	1,250 \$	
Wiring Charge	60 \$	
Tuff Kote		
Transffer Door Parts	\$ \$	
Remove/Refix Cushion & Upholstery Rear		
Remove/Refix Rear Windscreen Glass	The state of the s	
Remove/Refix Reverse Sensor	30 \$ 50 \$ NEC \$	_
Remove / refix Exhaust pipe	NEC S	
Advertisement Logo - 7 pcs TOTAL LABOUR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
IUIAL LABOUK		0,700.00
ESTIMATE TOTAL	\$	31,943.00
	Γ	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK 6/12/2022 1635 LJ3 CHECK ITEM PHOTOS
(AGNEST BOOK Value.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: