#### Estimate Report

# Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12 Singapore 737856 Tel: Fax: Email:

### INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD

PARTICULARS OF CLAIM

Claim Type:

TP

Ref. No:

Policy No:

5125513827

Date of Loss:

30/11/2022

Vehicle Reg. No.:

SLF6349G

Driveable? Third Party Vehicle No.: no SLP9174X

Driver Age:

Any Injuries?

no

Contact No:

Insured/Claimant:

ONG CHENG BOON

Driver:

ONG CHENG BOON

PARTS MODEL

Make/Model:

Mercedes-Benz, C200 Avant Vehicle Reg. Date:

01/09/2016

- WDD204

Vehicle Colour:

Engine Number: Odometer:

Chassis No: Total Loss?

WDD2050422R155614

Est. Duration of Repair(Day)

#### **DESCRIPTION OF ACCIDENT/LOSS**

Description of Accident/loss

Collision - Change/cross lane

Remarks:

Present Location:

Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts	A CONTRACT OF THE PROPERTY OF	17,843.00
Miscellaneous Items		765.00
Labour		2,930.00
Paintwork Labour		1,660.00
Towing		0.00
-	Gross Total(S\$):	23,198.00
	GST 7.00%(S\$):	1,623.86
	Nett Amount(S\$):	24,821.86

This claim is handled by: Sky Toh T C

## REPAIR DETAILS

Estima	ates On Pa	arts			
No.	Qty	Particulars	Amount	%Disc	After
		S. Ada wiz			Disc
1	1	FRONT DOOR LH	2,415.00	-20.00	1,932.00
2	1	REAR DOOR LH / Gue	2,450.00	-20.00	1,960.00
3	1	ROCKER PANEL LH X C Cyar	1,710.00	-10.00	1,539.00
4	1	REAR FENDER LH X	2,800.00	-20.00	2,240.00
5	1	REAR WHEEL RIM LH	1,650.00	-10.00	1,485.00
6	1	REAR SHOCK ABSORBER LH 🗶	950.00	-10.00	855.00
7	1	REAR LOWER ARM LH	880.00	-10.00	792.00
_8	1	REAR THRUST ARM LH X	850.00	-10.00	765.00
9	1	REAR KNUCKLE ARM LH 🦪	1,380.00	-10.00	1,242.00
_10	1	REAR CENTRE LOWER CROSSMEMBER 💢	3,300.00	-10.00	2,970.00
11	1	REAR BUMPER X JUST	2,050.00	-20,00	1,640.00
_12	1	REAR BUMPER SIDE RETAINER LH 🗶	85.00	-10.00	76.50
13	1	REAR BUMPER BRACKET LH	155.00	-10.00	139.50
14	1	REAR WINDSCREEN MOULDING X	230.00	-10.00	207.00

No.	Qty	Particulars ~	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS (1 SET)	45.00	0.00	45.00
2	2	REAR BUMPER SENSORS X	660.00	0.00	660.00
3	1	REAR WINDSCREEN SEALANT X	60.00	0.00	60.00
			Sub Total (S\$)	***************************************	765.00

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 X
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 ×
3	1	To Dismantle and Refit Rear Undercarriage.	220.00	0.00	220.00 ?
4	1	To Dismantle and Refit Rear Windscreen Glass.	120.00	0.00	120.00 X
5	2	To Transfer Door.	160.00	0.00	160.00
6	1	To Conduct Computer Wheel Alignment.	100.00	0.00	100.00 60
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,200.00	0.00	2,200.00 500

Gross Labour Cost (S\$) 2,930.00 620

No. Qty	Qty Particulars		Amount	%Disc	After
***************************************					Disc
1	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00
2	1	To Apply Undercoating On The Repaired and	80.00	0.00	80.00 ×
		Replaced Panels For Rust Protection.			, ,
3	1	To Spray painting on the Replaced and Repair	1,500.00	0.00	1,500.00 / 🕡

1000

Parts \$ 3445 Labour \$ 620 Pant \$ 1000 \$ 5065 - 25%

45 \$ 40,50/- (pls continus)