

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2337K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	CRACKED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER BEAM	SERVICEABLE	394.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	BOOTLID EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	BOOTLID EMBLEM - HYBRID	NECESSARY	24.30	24.30
1	BOOTLID EMBLEM - H	NECESSARY	28.00	28.00
1	REAR BUMPER LOWER CENTRE MOLDG	SERVICEABLE	155.00	-
1	REAR BUMPER STAY - LH	SERVICEABLE	138.10	-
1	REAR BUMPER STAY - RH	SERVICEABLE	138.10	-
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
	LESS 20% DISCOUNT		-388.21	-203.25
			1,552.84	813.00
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SERVICEABLE	180.00	-
1	REAR BOOTLID COMFORT LOGO (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID TEL.NOS LOGO (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID APPS LOGO (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			330.00	150.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	350.00
	SPRAY PAINT.		600.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		50.00	30.00
	CHECK WIRING.	NOT NECESSARY	50.00	-
			1,400.00	630.00
	GRAND TOTAL		3,282.84	1,593.00





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,250.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22012225/Nnp3m4

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser