

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22012228/KQY3Q2**Date:** 03/02/2023**REFERENCE**

Insured/Claimant: CALEB NG WEI CHUEN Policy No: SP2002751593-01
Date of Loss: 30/11/2022 Nature of Claim: OD Claim No: 202222008542

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF8922M**
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGGU219177
Reg. Date: 15/09/2016 (Man. Year: 2016) Chassis No: KMHD841CMHU238620
Colour: Metallic Silver Odometer: 94224 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$56,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Nexen 8 mm Rear Left Side: Nexen 8 mm
Front Right Side: Nexen 8 mm Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,843.60	1,376.10	467.50	25.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,050.00	400.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,293.60	2,426.10	867.50	26.34
+ GST 7.00/7.00% (S\$)	230.55	169.83	60.72	26.34
Nett Amount (S\$)	3,524.15	2,595.93	928.22	26.34

INSPECTION

Date of Assignment: 06/12/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 01/12/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 4.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8922M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Bent	300.00 F	*300.00 F
2	1		*1 PC FRT BUMPER RH RETAINER	Cracked	18.00 F	*18.00 F
3	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
4	1		*1 PC FRT BUMPER RH FOG LAMP	Cracked	95.00 F	*95.00 F
5	1		*1 PC FRT BUMPER RH FOG LAMP GARNISH	Missing	58.00 F	*58.00 F
6	1		*1 PC FRT BUMPER RH DAY RUNNING LAMP	Serviceable	85.00 F	*- F
7	1		*1 PC FRT BUMPER SIDE TOP RETAINER RH	Distorted	18.00 F	*18.00 F
8	1		*14 PCS FRT BUMPER SIDE TOP RETAINER RIVETS @2/PC	Necessary	28.00 F	*28.00 F
9	1		*1 PC FRT BUMPER LOWER REINFORCEMENT	Repair	40.00 F	*- F
10	1		*1 PC FRT BUMPER SPONGE	Serviceable	45.00 F	*- F
11	1		*1 PC FRT BUMPER REINFORCEMENT	Repair	200.00 F	*- F
12	1		*1 PC RH HEADLAMP	Cracked	490.00 F	*490.00 F
13	1		*1 PC RH HEADLAMP LOWER BRACKET	Cracked	20.00 F	*20.00 F
14	1		*1 PC FRT RH FENDER	Buckled	160.00 F	*160.00 F
15	1		*1 PC FRT RH FENDER DUST COVER	Cracked	40.00 F	*40.00 F
16	1		*6 PCS FRT RH FENDER DUST COVER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
17	1		*1 PC FRT SUPPORT TOP COVER	Serviceable	55.00 F	*- F
Sub Total (\$\$)						1,676.00 1,251.00
+ Margin on L,N Items 10.00/10.00% (\$\$)						167.60 125.10
Total Parts (\$\$)						1,843.60 1,376.10

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE DAMAGED FRT BUMPER,RH FENDER,BUMPER & ATTACHMENTS,PANEL BEAT & REPAIR RH FENDER APRON,INNER PANEL,BRACKETS	New	600.00	400.00
3	SPRAY PAINTING FRT BUMPER,FRT RH FENDER,FRT RH DOOR,FRT INNER PANEL,BONNET AND ALL AFFECTED AREAS	New	800.00	600.00
Gross Labour Cost (\$\$)			1,450.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >