



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4789B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	CUT	481.10	481.10
1	FRT BUMPER REINFORCEMENT	SERVICEABLE	1,136.70	-
1	FRT BUMPER MOULDING CENTRE UPPER	SERVICEABLE	368.50	-
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP RH	SERVICEABLE	2,110.30	-
1	FRT BUMPER TOWING COVER	SERVICEABLE	29.00	-
	LESS 20% DISCOUNT		-829.52	-100.62
			3,318.08	402.48
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.	NOT NECESSARY	60.00	-
			760.00	600.00
	GRAND TOTAL		4,078.08	1,002.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			800.00

Report Ref No. NS/INC22012230/Nvp3m4

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.