

ASS. REC. BY:

REF:

LPC / 22012234 / Kp

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

10/3 71 Rm & 6900L Car

Veh No: PC 2863CYr Regn: 09, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: YutongColour: WhiteSp. Reading: 232105

Eng/No: _____

C/No: LE YTAG E 63 E 101 6778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: As Line 275/70R22.50

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 3/12/22

Survey held at _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 7/3/2023

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S/Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. \$ _____

Parking:

Others:

TOTAL

ESTIMATED

VEHICLE NO: PC2963C YUTONG ZK6126

DATE 05.12.2022

No	Qty	PARTICULAR	AMOUNT S\$
1	1	FRONT CORNER PANEL LH <i>3800</i>	<i>1800</i> 5,843.00 ✓
2	1	FRONT PASSENGER DOOR <i>3800</i>	<i>1800</i> 3,522.00 ✓
3	1	FRONT HEADLAMP LH ASSY	<i>1800</i> 3,588.00 X
4	1	HEADLAMP COVER LH	<i>1800</i> 285.00 ✓
5	1	FRONT BUMPER	<i>1800</i> 2,855.00 X
6	1	SIDE REFLECTOR	<i>1800</i> 56.00 ✓
			\$ 16,149.00
Less 10%			\$ 1,614.90
			\$ 14,534.10

No	SPECAIL NETT	AMOUNT S\$
1	3 FRONT WINDSCREEN SEALANT	<i>1205N</i> 250.00
2	1 FRONT WINDSCREEN INNER SEAL	<i>605N</i> 150.00
		\$ 400.00

No	LABOUR & MISCELLANEOUS:	AMOUNT S\$
1	To remove damaged body parts with all necessary components/attach-ments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	3,800.00 <i>2000</i>
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	<i>800</i> 1,800.00
3	To remove,refix dashboard with all necessary components/attachments	<i>250.00</i> X
4	To remove,refix front windscreen glass and water test	800.00 <i>300</i>
5	To conduct headlamp alignment	50.00 <i>20</i>
		\$ 6,700.00

NOT WORK
CLP 86900h
Repair After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are on "without Prejudice" basis
- No illegal modifications are allowed
- Supply temporary details must be resurveyed and is subject to approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Menon
96910663

Menon@lkkauto.com